Configuration Activities

◆ Define the Inspection Types Setup in the SPRO

Path:

SPRO > Quality Management > Quality Inspection

> Inspection Lot Creation > Maintain Inspection Type

Inspection Type	Description	Integration
1	GR from Vendor	MM
3	In-Process	PP
4	GR from Production	PP