

Comprehensive Mission Report

Flight flight-4fb673922655692b61ac · DJI · generated 2026-09-20T12:51:42Z

How to read this: this report combines an automated incident summary, pre-emptive planning findings, and any fleet-wide recurring patterns for this flight -- all generated from recorded data and threshold-based checks, not a certified investigation. Technical terms (like detector names and triage labels) are explained where they first appear; each section also states its own confidence and limits.

Evidence-Backed Incident Summary

Local model enrichment: [available](#).

Hovering

Timestamp	Event
2026-03-18T11:23:08.000000Z	Hovering started
2026-03-18T11:23:09.000000Z	Hovering continued
2026-03-18T11:23:10.000000Z	Hovering continued
2026-03-18T11:23:11.000000Z	Hovering continued
2026-03-18T11:23:12.000000Z	Hovering continued
2026-03-18T11:23:13.000000Z	Hovering continued
2026-03-18T11:23:14.000000Z	Hovering continued
2026-03-18T11:23:15.000000Z	Hovering continued
2026-03-18T11:23:16.000000Z	Hovering continued
2026-03-18T11:23:17.000000Z	Hovering continued
2026-03-18T11:23:18.000000Z	Hovering continued
2026-03-18T11:23:19.000000Z	Hovering continued

Likely contributing factors:

- GPS signal weak

Recommended follow-up:

- Review the flight plan and ensure that the GPS signal is strong enough to support the mission.

The confidence level for this incident summary is 0.8. The limitations of this summary are that it is based on a limited number of data points and may not accurately represent the entire mission.

214 telemetry sample(s) analyzed (l2_canonical); 1 incident(s) detected.

Incident type	Count
operator_warning	1

Maneuver & Failure Findings

No maneuver or physics-threshold incidents were flagged on this flight.

Controller-Link Reliability

24 operator warning(s) referenced link/signal issues.

Timestamp	Warning text
2026-03-18T11:23:12.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:13.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:14.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:15.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:16.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:17.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:18.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:19.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:20.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).
2026-03-18T11:23:21.000000Z	GPS signal weak. Hovering unstable. Fly with caution (Code: 30008).

This platform records no audio between operator and controller. This section reports RF telemetry link reliability -- dropout gaps, link-related operator warnings, and signal-strength readings where captured -- as the closest measurable proxy.

Camera & Vision Reliability

No camera_frame visuals recorded for this flight.

This section covers measurable image quality (exposure, a coarse blur proxy) at captured frames. It does not classify terrain -- no terrain label exists anywhere in this platform's telemetry or vision data yet.

Pre-emptive Recommendations for Next Mission

- Link reliability findings this flight (0 dropout(s)) suggest reviewing antenna placement/orientation and considering a closer standoff distance or a redundant telemetry radio for the next mission in similar conditions.

Generated deterministically from recorded telemetry, detector output, and stored visual/census rows -- no audio channel, no terrain labels, and no causal fault diagnosis. Pattern-matched recommendations, not verified root causes. Requires human review before any operational change.

Fleet-Wide Recurring Pattern Matches

operator_warning — 5 flights, 5 incidents, max severity warning

operator_warning seen on 5 missions

Flight	Source log	Airframe
flight-1a1b914dc70e6d0c1b45	dji_csv_gps_jamming.csv	Mini 4 Pro S/N SYNEQZTKWBD84VG CB
flight-4fb673922655692b61ac	dji_csv_supplemental_gps_weak_recurrence.csv	Mini 4 Pro S/N SYNGQKJQTDDADWD CD
flight-e6139f8d710e387b95f5	dji_csv_gps_jamming_022.csv	Mini 4 Pro S/N SYNX48JEGBSZZD8W D
flight-8263737449e0891942da	dji_csv_motor_fail_recover_024.csv	Mini 4 Pro S/N SYNP8Z9KUCJV8WVJ V
flight-72f4078455c5b0bd0695	dji_csv_gps_weak_midair_end_028.csv	Mini 4 Pro S/N SYN3A9N8J6PYHE4C6

A shared signature is a reason to compare evidence across flights, not proof of a shared cause.

This document combines the evidence-backed incident report, pre-emptive planning findings, and any fleet-wide recurring-pattern matches for this flight. Each section carries its own scope and limitations -- read them individually before acting. A shared pattern signature is a reason to compare evidence across flights, not proof of a shared cause.