

ARM STM32F4 Peripheral Assignments -3

1. Write a program to print Float values through UART in terminal
2. Write a program to demonstrate printf functionality using UART
3. ADC demonstration using potentiometer
4. DAC demonstration using LED by varying LED intensity
5. Interface buzzer to MCU [Using PWM We have tested turning on]
Actuate buzzer for ON and OFF using IO pin
6. SPI demonstration using EEPROM as a slave

7. Write a program to transfer continuously on UART terminal temperature and relative humidity values of SHT21 by referring data sheet.

8. Write a menu driven program using serial UART terminal to start, display and stop temperature and relative humidity conversion.
Press 1 : Start temperature conversion
Press 2 : Display temperature value
Press 3 : Start Humidity conversion
Press 4 : Display humidity value
Press 5 : Stop Conversion