



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Scan Criteria

Tail Number: OY-CDC

Tail Number: OY-CDC

Model: P.68C

Manufacturer: Vulcanair S.p.A.

Description: Charlie

Total Hours: 6,007.00

Total Cycles: 10,072.00

Hours at Install:

Current Hours: 11,915.50

Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
CAT Practice	Maintenance documentation needs to be sent to CAT CAMO within 72 hours after aircraft has been released.		Mandatory	50,00H	5.978,50h/ 14-08-2026	21,50h	6.028,50h
Airworthiness Directive	Inspect stabilator, flap hinge and aileron hinge attachment shelves for corrosion.		Mandatory	100,00H	5.978,50h/ 14-08-2026	71,50h	6.078,50h
Airworthiness Directive	Inspect stabilator torque tube.		Mandatory	200,00H	5.978,50h/ 14-08-2026	171,50h	6.178,50h
Airworthiness Directive	Inspect LH and RH muffler assemblies for cracks/corrosion.		Mandatory	200,00H	5.978,50h/ 14-08-2026	171,50h	6.178,50h
Airworthiness Directive	Inspect fiberglass wing leading edges for cracks and debonding.		Mandatory	100,00H		5.907,00h/ OVD	100,00h
Airworthiness Directive	Inspect wing box structure between ribs 6 and 8 for cracks.		Mandatory	300,00H	4.536,10h/ 25-02-2020	1.170,90h/ OVD	4.836,10h
Airworthiness Directive	Carry out fuel tank selector control system actions.		Mandatory	100,00H	5.978,50h/ 14-08-2026	71,50h	6.078,50h
Airworthiness Directive	Inspect flight control cables for fraying.		Mandatory	100,00H	5.978,50h/ 14-08-2026	71,50h	6.078,50h
Airworthiness Directive	Inspect control wheel shaft ball joint.		Mandatory	200,00H 24cm		5.807,00h/ OVD	200,00h
Inspection	AMP review.		Mandatory	12m	5.654,40h/ 07-07-2025	2.35monthOVD	07-07-2026
Inspection	Check Certificate of Insurance		Mandatory	12m(1m)	5.801,70h/ 17-12-2025		
Inspection	ARC full documented review.		Mandatory				
Airworthiness Directive	Inspect upper and lower rudder hinges.		Mandatory	200,00H 12cm	5.978,50h/ 14-08-2026	171,50h/ 11.42month	6.178,50h/ 31-08-2027
Safety Information Bulletin	Test transponder altitude encoder every 24M.		Mandatory	24cm	5.796,70h/ 21-11-2025	14.39month	30-11-2027
Service Bulletin	Operational check of fuel selector control system.		Mandatory	100,00H	5.978,50h/ 14-08-2026	71,50h	6.078,50h
Service Bulletin	Inspect control wheel rod universal joint for cracks.		Mandatory	200,00H 24cm	5.427,00h/ 16-02-2024	380,00h/ OVD6.68monthOVD	5.627,00h/ 28-02-2026
Service Bulletin	Inspect fibreglass wing leading-edge ribs for cracks/disconnection.		Mandatory	100,00H	5.978,50h/ 14-08-2026	71,50h	6.078,50h
Service Bulletin	Inspect engine mount/wing attachment brackets for corrosion and cracks.		Mandatory	500,00H 24cm	5.796,70h/ 21-11-2025	289,70h/ 14.39month	6.296,70h/ 30-11-2027



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDC		Manufacturer: Vulcanair S.p.A.		Model: P.68C		Description: Charlie	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Service Bulletin	Inspect aircraft electrical system wiring throughout airframe.		Recommended	500,00H 24cm	5.796,70h/ 21-11-2025	289,70h/ 14.39month	6.296,70h/ 30-11-2027
Service Bulletin	Inspect flight control cables for fraying/wear/corrosion.		Mandatory	100,00H	5.978,50h/ 14-08-2026	71,50h	6.078,50h
Service Bulletin	Inspect stabilator torque tube joint.		Mandatory	200,00H	5.978,50h/ 14-08-2026	171,50h	6.178,50h
Service Bulletin	Verify min. clearance between engine oil cooler hoses and engine stacks when replacing oil cooler hoses.		Mandatory				
Service Bulletin	Inspect stabilator/flap/aileron hinge shelves for surface treatment & corrosion.		Mandatory	200,00H 12cm	5.978,50h/ 14-08-2026	171,50h/ 11.42month	6.178,50h/ 31-08-2027
Service Bulletin	Open inspection holes in wing underside near engine nacelles and inspect wing box for stringer/top-panel cracks.		Mandatory	300,00H	4.536,10h/ 25-02-2020	1.170,90h/ OVD	4.836,10h
Inspection	ARC extension.		Mandatory				
Replacement	Replace CO detector.		Mandatory	12m	5.931,30h/ 02-07-2026	9.48month	02-07-2027
Inspection	Annual inspection of ELT.		Mandatory	12m	5.978,50h/ 14-08-2026	10.87month	14-08-2027
Replacement	Replace Instrument Air Filter		Mandatory	500,00H(+10,00) 12m(1mcu mulative)	5.932,60h/ 02-07-2026	425,60h/ 9.48month	6.432,60h/ 02-07-2027
Replacement	Replace Instrument Air Filter		Mandatory	500,00H(+10,00) 12m(1mcu mulative)	-74,40h/ 02-07-2026	425,60h/ 9.48month	425,60h/ 02-07-2027
Replacement	Replace fire extinguisher.		Mandatory	120m	5.887,40h/ 29-05-2026	116.35month	29-05-2036
Inspection	Perform weighing and inspection of fire extinguisher.		Mandatory	100,00H 12cm	5.932,60h/ 02-07-2026	25,60h/ 10.42month	6.032,60h/ 31-07-2027
Replacement	Replace FAK Niveau 2		Mandatory				
Replacement	Replace FAK Niveau 3		Mandatory				
Overhaul	Engine fuel pump overhaul.		Mandatory	2.000,00H 14 4cm	22-08-2024	119.42month	31-08-2036
Overhaul	Engine fuel pump overhaul.		Mandatory	2.000,00H 14 4cm	18-07-2025	130.42month	31-07-2037
Inspection	Life vest visual inspection.		Mandatory	12cm	-74,40h/ 02-07-2026	10.42month	31-07-2027
Replacement	Life vest replacement.		Mandatory	120m	-1.815,00h/ 30-10-2017	13.39month	30-10-2027
Replacement	Life vest replacement.		Mandatory	120m	20-10-2016	1.06month	20-10-2026
Inspection	Life vest visual inspection.		Mandatory	12cm	02-07-2026	10.42month	31-07-2027
Replacement	Life vest replacement.		Mandatory	120m	20-10-2016	1.06month	20-10-2026



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDC		Manufacturer: Vulcanair S.p.A.		Model: P.68C		Description: Charlie	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Life vest visual inspection.		Mandatory	12cm	02-07-2026	10.42month	31-07-2027
Replacement	Life vest replacement.		Mandatory	120m	20-10-2016	1.06month	20-10-2026
Inspection	Life vest visual inspection.		Mandatory	12cm	02-07-2026	10.42month	31-07-2027
Replacement	Life vest replacement.		Mandatory	120m	20-10-2016	1.06month	20-10-2026
Inspection	Life vest visual inspection.		Mandatory	12cm	02-07-2026	10.42month	31-07-2027
Inspection	Life vest visual inspection.		Mandatory	12cm	02-07-2026	10.42month	31-07-2027
Replacement	Life vest replacement.		Mandatory	120m	20-10-2016	1.06month	20-10-2026
Replacement	Life vest replacement.		Mandatory	120m	20-10-2016	1.06month	20-10-2026
Inspection	Life vest visual inspection.		Mandatory	12cm	02-07-2026	10.42month	31-07-2027
Overhaul	Engine mount overhaul.		Mandatory	2.000,00H 14 4cm	16-02-2024	113.35month	29-02-2036
Overhaul	Engine mount overhaul.		Mandatory	2.000,00H 14 4cm	18-07-2025	130.42month	31-07-2037
Overhaul	Stabilizer torque tube overhaul.		Mandatory	1.500,00H 60c m	-393,00h/ 14-03-2025	1.107,00h/ 42.42month	1.107,00h/ 31-03-2030
Airworthiness Directive	Inspect engine exhaust valves and guides.		Mandatory	330,00H			
Service Bulletin	Inspect intake pipe and flange for cracks/fuel staining.		Mandatory	50,00H	14-08-2026		
Service Bulletin	Inspect intake/exhaust valves, springs, keys and rockers.		Mandatory	400,00H			
Airworthiness Directive	Inspect fuel injector fuel lines/clamps.		Mandatory	100,00H			
Inspection	Engine internal corrosion inspection.		Optional	60m(1m)	16-10-2017	41.81monthOVD	24-03-2023
Inspection	Valve inspection; Remove rockerbox cover and check for freedom of valve rockers.		Mandatory	400,00H(+10, 00)	02-07-2026		
Inspection	Engine overhaul.		Mandatory	2.000,00H(+2 00,00) 144m	16-02-2024	4.587,00h/ OVD112.94month	2.000,00h/ 16-02-2036
Service Bulletin	Inspect exhaust valve/guide condition for wear or carbon build-up.		Mandatory	300,00H	14-02-2024		
Inspection	Cylinder pressure test.		Mandatory	100,00H(+10, 00)	14-08-2026		
Airworthiness Directive	Hi-chrome valve guide inspection.		Mandatory	1.000,00H(+3 0,00)		4.587,00h/ OVD	2.000,00h
Airworthiness Directive	Hi-chrome valve guide inspection.		Mandatory	1.000,00H(+3 0,00)			
Inspection	Valve inspection; Remove rockerbox cover and check for freedom of valve rockers.		Mandatory	400,00H(+10, 00)	02-07-2026		
Inspection	Engine overhaul.		Mandatory	2.000,00H(+2 00,00) 144m	25-04-2024	115.23month	25-04-2036
Inspection	Engine internal corrosion inspection.		Optional	60m(1m)	25-04-2024	31.23month	25-04-2029



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDC		Manufacturer: Vulcanair S.p.A.		Model: P.68C		Description: Charlie	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Service Bulletin	Inspect intake pipe and flange for cracks/fuel staining.		Mandatory	50,00H	14-08-2026		
Airworthiness Directive	Inspect fuel injector fuel lines/clamps.		Mandatory	100,00H	14-08-2026		
Service Bulletin	Inspect exhaust valve/guide condition for wear or carbon build-up.		Mandatory	300,00H	14-02-2024		
Inspection	Cylinder pressure test.		Mandatory	100,00H(+10, 00)	14-08-2026		
Service Bulletin	Inspect intake/exhaust valves, springs, keys and rockers.		Mandatory	400,00H			
Airworthiness Directive	Inspect engine exhaust valves and guides.		Mandatory	330,00H			
Overhaul	Hartzell propeller overhaul.		Mandatory	2.400,00H 72 m	16-02-2024	40.94month	16-02-2030
Inspection	Inspect propeller blades, hub and visible parts for cracks, wear, corrosion and leaks.		Mandatory	100,00H 12cm		57.61monthOVD	30-11-2021
Overhaul	Hartzell propeller overhaul.		Mandatory	2.400,00H 72 m	18-07-2025	58month	18-07-2031
Inspection	Inspect propeller blades, hub and visible parts for cracks, wear, corrosion and leaks.		Mandatory	100,00H 12cm		33.61monthOVD	30-11-2023
Overhaul	Alternator overhaul, 2000H/144M.		Mandatory	2.000,00H 14 4m	-1.160,00h/ 16-02-2024	840,00h/ 112.94month	840,00h/ 16-02-2036
Replacement	Induction air filter replacement		Mandatory	100,00H(+10, 00) 12m(1m)	-28,50h/ 14-08-2026	5.935,50h/ OVD	71,50h
Overhaul	Fuel injector overhaul.		Mandatory	2.000,00H 14 4cm	15-11-2024	122.39month	30-11-2036
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	29-07-2025		
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)	29-07-2025		
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	05-06-2026		
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)	05-06-2026		
Service Bulletin	Inspect muffler assemblies for cracks and corrosion.		Mandatory	200,00H	-6.035,50h/ 14-08-2026	5.835,50h/ OVD	-5.835,50h
Overhaul	Engine starter overhaul.		Mandatory	2.000,00H 14 4m	-287,80h/ 16-02-2024	4.587,00h/ OVD112.94month	1.712,20h/ 16-02-2036
Replacement	Vacuum pump replacement, 72M.		Mandatory	72m	16-02-2024	40.94month	16-02-2030
Overhaul	Alternator overhaul, 2000H/144M.		Mandatory	2.000,00H 14 4m	18-07-2025	130month	18-07-2037
Replacement	Induction air filter replacement		Mandatory	100,00H(+10, 00) 12m(1m)	551,50h/ 14-08-2026	651,50h	651,50h

Aircraft Status



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDC		Manufacturer: Vulcanair S.p.A.		Model: P.68C		Description: Charlie	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Overhaul	Fuel injector overhaul.		Mandatory	2.000,00H 14 4cm	416,40h/ 18-07-2025	2.234,30h/ 130.42month	2.416,40h/ 31-07-2037
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	18-07-2025		
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)			
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)	15-11-2024		
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	10-03-2026		
Service Bulletin	Inspect muffler assemblies for cracks and corrosion.		Mandatory	200,00H	551,50h/ 14-08-2026	751,50h	751,50h
Overhaul	Engine starter overhaul.		Mandatory	2.000,00H 14 4m	876,30h/ 18-07-2025	2.243,30h/ 130month	2.876,30h/ 18-07-2037
Replacement	Vacuum pump replacement, 72M.		Mandatory	72m	14-08-2026	70.87month	14-08-2032
Overhaul	Propeller governor overhaul.		Mandatory	2.000,00H 14 4m	16-02-2024	112.94month	16-02-2036
Overhaul	Propeller governor overhaul.		Mandatory	2.000,00H 14 4m	06-11-2025	133.61month	06-11-2037
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	-580,00h/ 16-02-2024	29.32month	28-02-2029
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	-6.587,00h/ 16-02-2024	29.32month	28-02-2029
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	-580,00h/ 16-02-2024	29.32month	28-02-2029
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	-580,00h/ 16-02-2024	29.32month	28-02-2029
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	-6.587,00h/ 16-02-2024	29.32month	28-02-2029
Overhaul	Engine fuel pump overhaul.		Mandatory	2.000,00H 14 4cm			
Inspection	Start booster inspection.		Mandatory	500,00H		500,00h	500,00h
Replacement	Engine mount vibration isolator replacement.		Mandatory	2.000,00H 14 4cm		4.007,00h/ OVD	2.000,00h
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	234,30h/ 18-07-2025	46.42month	31-07-2030
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	234,30h/ 18-07-2025	46.42month	31-07-2030
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	234,30h/ 18-07-2025	46.42month	31-07-2030
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	234,30h/ 18-07-2025	46.42month	31-07-2030
Replacement	Engine flexible hoses replacement, 5 years		Mandatory	60cm	234,30h/ 18-07-2025	46.42month	31-07-2030



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDC		Manufacturer: Vulcanair S.p.A.		Model: P.68C		Description: Charlie	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Overhaul	Engine fuel pump overhaul.		Mandatory	2.000,00H 14 4cm			
Inspection	Start booster inspection.		Mandatory	500,00H		500,00h	500,00h
Replacement	Engine mount vibration isolator replacement.		Mandatory	2.000,00H 14 4cm		2.000,00h	2.000,00h

*** End of Document ***