```
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[STORE] saved
[STATE] SLEEP timer=60 s
ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":729,"heap"
:336332,"sensor_ok":true}
[FAULT] firmware hang
ets Jul 29 2019 12:21:46
```

```
rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[STORE] saved
[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
```

```
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":730,"he
ap":336332,"sensor_ok":true}
[FAULT] power loss DURING save
ets Jul 29 2019 12:21:46

rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=SOFTWARE_RESET
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[STORE] saved
[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
```

```
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":831,"he
ap":336332,"sensor_ok":true}
[STORE] saved
[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[STORE] saved
[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
```

```
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":833,"h
eap":336332,"sensor_ok":true}
[FAULT] firmware hang
E (21735) task_wdt: Task watchdog got triggered. The following tasks did not
reset the watchdog in time:
E (21735) task_wdt:  - loopTask (CPU 1)
E (21735) task_wdt: Tasks currently running:
E (21735) task_wdt: CPU 0: IDLE0
E (21735) task_wdt: CPU 1: loopTask
E (21735) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0


Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED




ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
```

load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[CLI] ERROR unknown command
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
[FAULT] firmware hang
E (14974) task_wdt: Task watchdog got triggered. The following tasks did not
reset the watchdog in time:
E (14974) task_wdt: - loopTask (CPU 1)
E (14974) task_wdt: Tasks currently running:
E (14974) task_wdt: CPU 0: IDLE0
E (14974) task_wdt: CPU 1: loopTask
E (14974) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0

Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED

ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00

mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
[FAULT] firmware hang
E (24310) task_wdt: Task watchdog got triggered. The following tasks did not
reset the watchdog in time:
E (24310) task_wdt: - loopTask (CPU 1)
E (24310) task_wdt: Tasks currently running:
E (24310) task_wdt: CPU 0: IDLE0
E (24310) task_wdt: CPU 1: loopTask
E (24310) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0

Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED

ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00

```
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[CLI] ERROR unknown command
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
[FAULT] firmware hang
E (15804) task_wdt: Task watchdog got triggered. The following tasks did not
reset the watchdog in time:
E (15804) task_wdt:  - loopTask (CPU 1)
E (15804) task_wdt: Tasks currently running:
E (15804) task_wdt: CPU 0: IDLE0
E (15804) task_wdt: CPU 1: loopTask
E (15804) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0


Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED




ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
```

clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[CLI] ERROR unknown command
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:335276,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:335276,"sensor_ok":true}
[FAULT] firmware hang
E (24711) task_wdt: Task watchdog got triggered. The following tasks did not
reset the watchdog in time:
E (24711) task_wdt: - loopTask (CPU 1)
E (24711) task_wdt: Tasks currently running:
E (24711) task_wdt: CPU 0: IDLE0
E (24711) task_wdt: CPU 1: loopTask
E (24711) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0

Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED

ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)

```
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[CLI] ERROR unknown command
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336284,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336284,"sensor_ok":true}
[FAULT] firmware hang
E (16317) task_wdt: Task watchdog got triggered. The following tasks did not
reset the watchdog in time:
E (16317) task_wdt:  - loopTask (CPU 1)
E (16317) task_wdt: Tasks currently running:
E (16317) task_wdt: CPU 0: IDLE0
E (16317) task_wdt: CPU 1: loopTask
E (16317) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0


Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED




ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46
```

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
[CLI] ERROR unknown command
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"

:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336172,"sensor_ok":true}

{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap":336172,"sensor_ok":true}
[FAULT] firmware hang
E (18639) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
E (18639) task_wdt: - loopTask (CPU 1)
E (18639) task_wdt: Tasks currently running:
E (18639) task_wdt: CPU 0: IDLE0
E (18639) task_wdt: CPU 1: loopTask
E (18639) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0

Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED

ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":833,"heap"
:336332,"sensor_ok":true}
[FAULT] power loss DURING save
ets Jul 29 2019 12:21:46

rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4

```
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=SOFTWARE_RESET
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":false,"counter":
933,"heap":336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":false,"counter":
933,"heap":336332,"sensor_ok":true}
[STORE] saved
[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":934,"h
```

eap":336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":934,"h
eap":336332,"sensor_ok":true}
[FAULT] firmware hang
E (19717) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
E (19717) task_wdt: - loopTask (CPU 1)
E (19717) task_wdt: Tasks currently running:
E (19717) task_wdt: CPU 0: IDLE0
E (19717) task_wdt: CPU 1: loopTask
E (19717) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0

Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED

ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":934,"heap"

:336332,"sensor_ok":true}
[FAULT] firmware hang
E (7121) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
E (7121) task_wdt: - loopTask (CPU 1)
E (7121) task_wdt: Tasks currently running:
E (7121) task_wdt: CPU 0: IDLE0
E (7121) task_wdt: CPU 1: loopTask
E (7121) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0

Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED

ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":934,"heap"
:336332,"sensor_ok":true}
[FAULT] firmware hang

E (12969) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
E (12969) task_wdt: - loopTask (CPU 1)
E (12969) task_wdt: Tasks currently running:
E (12969) task_wdt: CPU 0: IDLE0
E (12969) task_wdt: CPU 1: loopTask
E (12969) task_wdt: Aborting.

abort() was called at PC 0x400dbf11 on core 0

Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED

ELF file SHA256: 1e9f6d28d20fb872

ets Jul 29 2019 12:21:46

rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=INT_WDT
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":934,"heap":336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":false,"counter":934,"heap":336332,"sensor_ok":true}
[FAULT] power loss DURING save

```
ets Jul 29 2019 12:21:46

rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=SOFTWARE_RESET
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":false,"counter":1
034,"heap":336332,"sensor_ok":true}
[FAULT] power loss DURING save
ets Jul 29 2019 12:21:46

rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=SOFTWARE_RESET
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
```

```
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":false,"counter":1
134,"heap":336332,"sensor_ok":true}
[FAULT] power loss DURING save
ets Jul 29 2019 12:21:46

rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=SOFTWARE_RESET
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":false,"counter":1
234,"heap":336332,"sensor_ok":true}
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":false,"counter":1
234,"heap":336332,"sensor_ok":true}
[STORE] saved
[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
```

```
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":1235,"h
eap":336332,"sensor_ok":true}
[STORE] saved
[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":1236,"h
eap":336332,"sensor_ok":true}
[STORE] saved
```

[STATE] SLEEP timer=3 s
ets Jul 29 2019 12:21:46

rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
configsip: 0, SPIWP:0xee
clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
mode:DIO, clock div:2
load:0x3fff0030,len:1156
load:0x40078000,len:11456
ho 0 tail 12 room 4
load:0x40080400,len:2972
entry 0x400805dc
[BOOT] reset_reason=DEEP_SLEEP
[WAKE] cause=4
[WDT] enabled timeout=4000 ms
Commands:
  help
  status
  sensor
  relay on
  relay off
  save
  sleep <seconds>
  hang
  powerloss
  reboot
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":1237,"h
eap":336332,"sensor_ok":true}