



ASSET RECORD FOR JOB No. 96133

Inspection date: 26/02/2026

Purchase Order:

Customer name: Shangri-La Hotel Cairns

Email: michelle.davis@shangri-la.com

Site name: Shangri-La Hotel - Pierpoint Road Cairns

Site address: Pierpoint Road , Cairns QLD 4870

Contact: Michelle Davis

Asset Register - 02.1 Emergency Warning Systems - AS1851.2012 A1

Asset ID	Building Location	Panel Number	Equipment Number	Zone Feed	5 Yearly Due	Service Level	Date	Pass / Fail
96015	GF Pier West Boardwalk	Node 1 - Pier Shopping Centre	-	-	-	Monthly	26/02/2026	Fail
Test Readings							Result	
Work Order Number							FEB 26 SM FIP (M)	
Site Attendance Record Number							A106710	
TABLE 6.4.3.1 MONTHLY SERVICE SCHEDULE EMERGENCY WARNING SYSTEM							2026-02-26	
--- 1.2 Zone Block plan - INSPECT zone block plans to ensure that they are securely mounted and legible and supplementary zone drawings, if provided, are available and legible.							Fail	
--- 1.3 Control and indicating equipment - INSPECT the warning system panel, and— (a) ensure that it is clearly visible, readily accessible and free from dust and contaminants;							Pass	
--- 1.3 Control and indicating equipment - INSPECT the warning system panel, and— (b) where a panel is obscured by a door, CHECK that the door is correctly labelled;							Pass	
--- 1.3 Control and indicating equipment - INSPECT the warning system panel, and— (c) where manual call points use replaceable frangible elements, ENSURE that at least one replacement element and a tool is available for replacing the element where required.							Pass	
--- 1.4 Battery enclosure - Where vented batteries are used, INSPECT the battery enclosure for evidence of corrosion.							Pass	
--- 1.5 Emergency warning system test - SIMULATE an alarm condition and confirm that the required warning signal(s) operate. NOTE: It is recommended that the warden intercom system is used by the floor wardens to confirm the operation of the warning signals.							Pass	
Have all previously reported defects been rectified							No	
Queensland Buildings Only: I hereby acknowledge that the mentioned system above has been routinely serviced in accordance with Australian Standard AS1851-2012 Amendment 1 & AS2293.2 and that the information on this report is true and correct. This record does not infer compliance of all applicable building and fire legislation within the relevant jurisdiction - Queensland Buildings Only - Maintenance complies with QDC, MP6.1:							Yes	
Queensland Buildings Only: I hereby acknowledge that the mentioned system above has been routinely serviced in accordance with Australian Standard AS1851-2012 Amendment 1 & AS2293.2 and that the information on this report is true and correct. This record does not infer compliance of all applicable building and fire legislation within the relevant jurisdiction - Queensland Buildings Only - System is in proper working order:							Yes	

Notes	No new defects identified.
	Previously identified and quoted (?) defects from past tests yet to be rectified: - EVAC plan does not show correct layout of building - EOL resistor is installed on every zone and fault occurring on zone 2. Requires investigation

All works above have been carried out in accordance with the relevant Australian Standards, Codes of Practice and the information on this data report is true and correct. This record does not infer compliance with all applicable building and fire safety legislation within the relevant jurisdiction.

Technician (Print Name): Scott Eagle-Rowe Licence No. Customer (Print Name):

15422243

Technician (Signature): Customer (Signature):