No.	Status	Date
HIS-2013-0451-DFR-1	Issued	2013-12-09

Daily Field Report 1 - UT Thickness Re-measurement - Reflux Lines 3-RF-101 and 2-RF-102

Scope and Responsibilities

Kevin Doucette, acting as lead UT technician, performed a UT thickness survey on reflux lines 3-RF-101 and 2-RF-102 located within the ATU-100. The objective was to conduct thickness re-measurements to monitor asset integrity.

All activities were executed under the authority of QSCP-WP-2013-12096. The technician is responsible for the accurate acquisition of thickness data and adherence to site safety and technical requirements.

Technical Basis and Procedures

The inspection was performed under the requirements of QSCP-NDT-001 Rev 2 and HIS-UT-002 Rev 1. These documents govern the methodology for ultrasonic thickness measurement and the specific requirements for the CUI program, including insulation management.

Measurement techniques and acceptance criteria were applied in accordance with ASTM E797. The A312 TP316 material of the subject lines required the use of the stainless-steel velocity setting on the equipment.

Equipment and Calibration

Thickness measurements were obtained using a Krautkrämer DMS 2 0317. The instrument's validity is confirmed by HIS-CAL-13-088.

Field calibration and standardization were performed using the HIS-STB-02 calibration block to ensure measurement accuracy prior to the survey of the reflux lines.

Inspection Results - 3-RF-101

Line 3-RF-101, constructed from A312 TP316 with a nominal thickness of 5.49 mm and an outer diameter of 88.9 mm, was surveyed. The design limits for this line are 517 kPa(g) and 104 °C.

The measured thicknesses were compared against the retirement thickness of 2.41 mm. All readings were found to be above this t-min value.

Inspection Results - 2-RF-102

Line 2-RF-102, constructed from A312 TP316 with a nominal thickness of 3.91 mm and an outer diameter of 60.3 mm, was surveyed. The design limits for this line are 517 kPa(g) and 104 °C.

The measured thicknesses were compared against the retirement thickness of 2.16 mm. All readings were found to be above this t-min value.

Sign-off	Name	Function	Date	Signature
Prepared	Kevin Doucette	lead UT technician, SNT-TC-1A UT Level II	2013-12-09	_____