#Write an assembly language program to clear all the flag bits in flag register.

MVI A, 00;

ADI 01;

HLT;