

Notice of Product Changes

No.: NWY-PCN-20250714002

Title	Firmware Version Changes	
Product	N706B	
Review No.	NWY-PCN-20250714002	
Change		
Distinguished customers:		
Thank you for your long-term trust and support in Neoway products. In order to cater to market and application demand as well as to provide better products with more stable performance, we made the following change:		
From N706B-A07-STD-OE_CN1X_ITRI-008 to N706B-A07-STD-OE_CN1X_ITRI-009		
➤ Modify the FOTA partition to Fixe the issue When FOTA update is happening and then remove the power. Module does not recover.		
➤ Reduced the Spi clock speed from 52M to 26M		
➤ Fixed the CIMI command response issue		
➤ Implement NITZ virtual AT command		
Because we modify the FOTA partition,so module can not fota upgrade between N706B-A07-STD-OE_CN1X_ITRI-008 and N706B-A07-STD-OE_CN1X_ITRI-009		
Difference		
Item	Before	After
SDK version	N706B-A07-STD-OE_CN1X_ITRI-008	N706B-A07-STD-OE_CN1X_ITRI-009
Hardware version	No changes	No changes
Purchase code	No changes	No changes
Release Time		
Deadline	2025-7-14	
Processing Scheme of Finished Products		
Products that the customers have delivered.	Mandatorily update to N706B-A07-STD-OE_CN1X_ITRI-009	
Products that are being produced by the customers.	Mandatorily update to N706B-A07-STD-OE_CN1X_IN-009	

Products that are undelivered to the customers by Neoway.	It is recommended to use the module with the firmware N706B-A07-STD-OE_CN1X_ITRI-009
Approved by	
PM	Xu
Document Controller	Tang
Distributed to	
Distributed to	Customers, Sales Dept., Technical Support Dept., Planning Dept., Quality Dept.

This notice is circulated through emails and signature is not a must.
