

payout_wire_until_land() - landing loop (one pass = one static step)

Repeats until the PLET clearance is below 5 m; then the wire-slackening loop starts

