

FIELD AUDIT SCAN

FAS-2026-19 | image-only inspection record

Scope

The field audit covered line B between station 12 and station 19 on 14 October 2026. The report identifier is FAS-2026-19; FAS-2026-91 is a training form. Each finding was measured twice by different auditors.

Boundary

This scanned record contains no worker phone numbers, gate codes or system passwords. It is only for OCR and retrieval evaluation.

1. VERIFIED FINDINGS

measured values

Reading

At marker 16 the verified wear depth measured 27 mm. The nearby 34 mm value belongs to a calibration block and is not a real finding.

Threshold

Manual engineering review is required when a verified depth reaches 25 mm or growth exceeds 5 mm between audits.

Action

The 27 mm finding was entered into the engineering queue under an interim restriction; the record does not state the asset failed.

2. 中文复核记录

扫描中文段落

区段信息

中文复核记录的区段编号为 CN-AUDIT-53,检查范围对应 B 线 16 号标记附近。培训页中的 CN-AUDIT-35 是演示编号,不能作为正式引用。

处置条件

当磨损深度达到 25 毫米或两次审计增长超过 5 毫米时进入工程复核。一次异常读数只保留观察记录。

复查时间

下一次现场复查安排在 2026 年 10 月 21 日 06:30,由资产完整性组负责。10 月 20 日是设备校准日期,不是现场复查时间。

3. DEFECT REGISTER

scanned table

Table

Location	Depth	Change	Status	Owner
B-16	27 mm	+6 mm	ENGINEERING REVIEW	Integrity Team
B-14	13 mm	+1 mm	MONITOR	Night Audit
B-18	9 mm	NEW	VERIFY	Ultrasonic Team

Reading note

The status belongs to the same row as the location. B-16 is the only row assigned to ENGINEERING REVIEW.

4. ACTION AND LIMITS

deadlines and negative evidence

Deadline

The engineering disposition is due by 18:00 on 18 October 2026. The planning meeting on 17 October is not the disposition deadline.

Rejected draft

A draft note proposed a 30 mm review threshold. Engineering rejected it; the approved threshold remains 25 mm.

Unsupported

No staff phone number, depot password or residential address is present. The correct response to those questions is no answer.