WORKPLACE RISK ASSESSMENT SYSTEM PRINT RISK ASSESSMENT

Print | Close

To export as PDF, Please follow the steps: 1. Right-click on the browser; 2. Select the print option and select LANDSCAPE layout; 3. Set the scale to 75% under more settings and save it as a PDF.

Risk Assessment Details ID: RA_EEE_103341 Rev No: 1 Draft ID: 0				
User's School/ Department/ Student Activity Group:	School of Electrical & Electronic Engineering	Project Title:	DIP E012: A Smart Battery Charger and Monitoring System	
Workplace:	School of Electrical & Electronic Engineering	Other workplace:	-	
Location:	Project Lab (S2-B4- 01/02)	Conducted By:	NG HWEE YANG MEG(HNG045@e.ntu.edu.sg);MAK SIN HUA(MAKS0008@e.ntu.edu.sg);SEAN LOW CHUN WAI(SLOW027@e.ntu.edu.sg);TAN REN XIAN, GLEN(GTAN081@e.ntu.edu.sg);BAID SHAURYA(BAID0003@e.ntu.edu.sg);GOH ZHI PING(GOHZ0046@e.ntu.edu.sg);KIRBY YEO KER BI(E210120@e.ntu.edu.sg)	
Approved By:	Chan Pak Kwong (EPKCHAN@ntu.edu.sg)	Submitted By/Submitted Date:	NG HWEE YANG MEG/25-Jan-23	
Approved Date:	26-Jan-23	Next Review Date:	25-Jan-26	
Status:	Approved	Comments:	NA	

1. Hazard Identification				2. Risk Evaluation	
1a.	1b.	1c.	1d.	1e.	2a.
No.	Work Activity	Hazard	Sub Hazard	Possible Accident/III Health & Person-at-Risk	Existing Risk Contro
1	Soldering	Psychosocial	Fatigue	Occupational asthma or respiratory illness	Always use fume extractor provided. Ensure the fume hood located to draw the furning and smoke away from users into the extraction unit. Recommended to we masks.
		Physical	Contact with heated surface	Burns/ scalds	Briefing by Lab Staff before usage. Only the person using switch on the soldering station.

					Check for any damag equipment. If any damage is visible, do switch the soldering station on, report the damage to the Lab St and request for equipment replaceme
		Psychosocial	Fatigue	Sprains, strains	Ensure the seating ar lighting is adequate for your needs. If the job is taking long than expected take regular breaks.
2	Use of electrical equipment	Electrical	Contact with electrical energy	Others:Electric Shock	Briefing by Lab Staff before usage. Check for any damag equipment. If any damage is visible, do switch the equipment report the damage to Lab Staff and request equipment replaceme Ensure the power sur is switched off before making any changes the circuit. Ensure work area is fi of any obstructions.
		Physical	Slips, trips and falls hazard	Others:Bodily injuries (bruises)	Ensure good housekeeping practice and extension cords/wires are prope laid or tapped down
3	Wiring up the electrical/electronic circuitry	Electrical	Contact with electrical energy	Others:Electric Shock	Ensure power supply off before any connections adjustme Check that the power supply readings are s according to compone operating range. Ask group members t ensure proper circuitry linkage before switchi on the power supply.
4	Usage of hand tools	Physical	Others:Cut, Bruises	Sprains, strains	Briefing by Lab Staff before usage. Ensure users are properties of the properties of the properties of the project of the proj

		Psychosocial	Fatigue	Sprains, strains	Ensure that activity is conducted in a well-lit environment and appropriate height. Take breaks as requir Buddy with another us to take turns
5	Replace faulty equipment with good working set	Physical	Others:Accidental dropping of equipment during shifting	Others:Foot Injury	Lab staff use a waist- trolley to move slowly carefully when transporting the equipment.