

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

PROPERTY & LOSS SUMMARY

FIELD	VALUE
Policy Number	PROP-2026-88231
Insured	James Okafor
Property Address	142 Birchwood Lane, Riverton
Date of Loss	06/10/2026
Cause of Loss	Wind-driven rain / roof penetration
Probable Total Loss	\$41,850.00

CAUSE OF LOSS VERIFICATION

☒ Wind ☐ Nail
☐ Fire ☐ Water - Plumbing
☒ Water - Weather ☐ Theft
☐ Vandalism ☐ Other

ROOM INSPECTION -- LIVING ROOM

FIELD	READING
Room / Area	Living Room
Moisture Reading	25%
Damage Type	Water intrusion
Photo Reference	IMG-2001.jpg through IMG-2003.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- KITCHEN

FIELD	READING
Room / Area	Kitchen
Moisture Reading	32%
Damage Type	Drywall staining
Photo Reference	IMG-2002.jpg through IMG-2004.jpg
Recommended Action	Remove and replace affected material; dry/cut and monitor 72 hrs.

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- PRIMARY BEDROOM

FIELD	READING
Room / Area	Primary Bedroom
Moisture Reading	39%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2003.jpg through IMG-2005.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster Meridian Mutual
 FROM: Field Inspector K. Albers, Lic. #IL 4471
 SUBJECT: Claim CLM-2026-41297 Policy PROP 2026-8823 Property Loss Inspection Report

ROOM INSPECTION -- BEDROOM 2

FIELD	READING
Room / Area	Bedroom 2
Moisture Reading	45%
Damage Type	Flooring buckling
Photo Reference	IMG-2026-113 through IMG-2026-119
Recommended Action	Remove and replace affected material; dry out and monitor 24 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	20 sq ft	\$9.00	\$180.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	2 days	\$15.00	\$30.00
Paint & finish	45 sq ft	\$2.75	\$123.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #11-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BATHROOM

FIELD	READING
Room / Area	Bathroom
Moisture Reading	53%
Damage Type	Insulation saturation
Photo Reference	IMG-2005.jpg through IMG-2007.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	2 days	\$65.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- UTILITY

FIELD	READING
Room / Area	Basement -- Utility
Moisture Reading	20%
Damage Type	Structural warping
Photo Reference	IMG-2006.jpg through IMG-2008.jpg
Recommended Action	Remove and replace affected material; dry-out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- STORAGE

FIELD	READING
Room / Area	Basement -- Storage
Moisture Reading	27%
Damage Type	Ceiling sag
Photo Reference	IMG-2007.jpg through IMG-2009.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- ATTIC

FIELD	READING
Room / Area	Attic
Moisture Reading	34%
Damage Type	Electrical exposure risk
Photo Reference	IMG-2008.jpg through IMG-2010.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
 FROM: Field Inspector K. Algers, LEO. #014471
 SUBJECT: Claim CLM 2026-41207 - Policy PROP 2026-8623 - Property Loss Inspection Report

ROOM INSPECTION -- GARAGE

FIELD	READING
Room Area	1044 sq.
Moisture Reading	41
Barrel Type	water resistant
Photo Reference	10-21-2016-4-21-2016-10-21-2016
Recommended Action	Repair and replace with dry materials; dry out and render 32 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
drywall removal & replacement	1044 sq.	\$2.00	\$2088.00
insulation replacement	1044 sq.	\$2.00	\$2088.00
flooring - exterior repair	1044 sq.	\$2.00	\$2088.00
drywall replacement	1044 sq.	\$2.00	\$2088.00
insulation repair - exterior	1044 sq.	\$2.00	\$2088.00
paint & trim	1044 sq.	\$2.00	\$2088.00

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- ROOF

FIELD	READING
Room / Area	Exterior -- Roof
Moisture Reading	48%
Damage Type	Drywall staining
Photo Reference	IMG-2010.jpg through IMG-2012.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- SIDING

FIELD	READING
Room / Area	Exterior -- Siding
Moisture Reading	55%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2011.jpg through IMG-2013.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & Finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster Meridian Mutual
 FROM: Field Inspector K. Alders, Lic. #IL-34471
 SUBJECT: Claim CLM-2026-41207 Policy PROP-2026-88231 Property Loss Inspection Report

ROOM INSPECTION -- CRAWL SPACE

FIELD	READING
Room / Area	Crawl Space
Moisture Reading	12%
Damage Type	Flooring buckling
Photo Reference	IMG-2012.jpg through IMG-2014.jpg
Recommended Action	Remove and replace affected material; dry out and retest 42 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	10 sq ft	\$6.00	\$60.00
Insulation replacement	60 sq ft	\$2.40	\$144.00
Flooring subfloor repair	10 sq ft	\$24.00	\$240.00
Mold remediation labor	2 hrs	\$250.00	\$500.00
Dehumidifier rental (per day)	1 day	\$250.00	\$250.00
Paint & finish	40 sq ft	\$1.75	\$70.00

TO: Claims Adjuster - Meridian Mutual
 FROM: Field Inspector K. Alders, Lic. #IL 4471
 SUBJECT: Claim CLM 2026 41207 - Policy PROP 2026 88231 - Property Loss Inspection Report

ROOM INSPECTION -- LIVING ROOM

FIELD	READING
Room / Area	Living Room
Moisture Reading	29%
Damage Type	Infiltration saturation
Photo Reference	IMG-2017.jpg through IMG-2018.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
3000-1-298-001 4 101400000	45 sq ft	\$6.20	\$279.00
3000-40 1 101400000	60 sq ft	\$2.85	\$171.00
1 101400000 1 101400000	20 sq ft	\$9.10	\$273.00
3000-20000000 10000	4 hrs	\$86.00	\$344.00
3000-20000000 10000 10000	2 days	\$65.00	\$130.00
1 101400000	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- KITCHEN

FIELD	READING
Room / Area	Kitchen
Moisture Reading	36%
Damage Type	Structural warping
Photo Reference	IMG-2014.jpg through IMG-2016.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- PRIMARY BEDROOM

FIELD	READING
Room / Area	Primary Bedroom
Moisture Reading	43%
Damage Type	Ceiling sag
Photo Reference	IMG-2015.jpg through IMG-2017.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster Meridian Mutual
 FROM: Field Inspector K. Wilson, DSI, FOL-4431
 SUBJECT: Claim CLM 2026 41207 Follow PROS 2026 8824 Property Loss Inspection Report

ROOM INSPECTION -- BEDROOM 2

FIELD	READING
Room Area	Bedroom 2
Moisture Reading	0%
Surface Type	Electrical, exposed, plug
Photo Reference	IMG-2026-07-07 13:10:10 IMG-2026-07-07
Recommended Action	Remove and replace affected material, dry out and monitor 24 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq. ft.	\$46.20	\$2,079.00
Insulation replacement	80 sq. ft.	\$21.85	\$1,748.00
Flooring subfloor repair	30 sq. ft.	\$9.10	\$273.00
Mold remediation labor	4 hrs.	\$334.00	\$1,336.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	55 sq. ft.	\$14.35	\$789.25

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #11-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BATHROOM

FIELD	READING
Room / Area	Bathroom
Moisture Reading	57%
Damage Type	Water intrusion
Photo Reference	IMG-2017.jpg through IMG-2019.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
 FROM: Field Inspector K. Algers, Lic. #14 4474
 SUBJECT: Claim CLM 2026-8823 Policy PROP 2026-8823 Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- UTILITY

FIELD	READING
Basement Water	Basement - 14.1000
Basement Humidity	44
Basement Temp	64.0000
Utility Room Temp	64.0000
Basement Humidity	44
Basement Temp	64.0000

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
1. 1/2" x 6" x 8' Plywood	100.00	0.45	45.00
2. 1/2" x 6" x 8' Plywood	100.00	0.45	45.00
3. 1/2" x 6" x 8' Plywood	100.00	0.45	45.00
4. 1/2" x 6" x 8' Plywood	100.00	0.45	45.00
5. 1/2" x 6" x 8' Plywood	100.00	0.45	45.00
6. 1/2" x 6" x 8' Plywood	100.00	0.45	45.00

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 Policy PROP-2026-88231 Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- STORAGE

FIELD	READING
Room / Area	Basement -- Storage
Moisture Reading	31%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2019.jpg through IMG-2021.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & Finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #1L-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- ATTIC

FIELD	READING
Room / Area	Attic
Moisture Reading	38%
Damage Type	Flooring buckling
Photo Reference	IMG-2020.jpg through IMG-2022.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- GARAGE

FIELD	READING
Room / Area	Garage
Moisture Reading	45%
Damage Type	Insulation saturation
Photo Reference	IMG-2021.jpg through IMG-2023.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 Policy PROP-2026-88231 Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- ROOF

FIELD	READING
Room / Area	Exterior -- Roof
Moisture Reading	52%
Damage Type	Structural warping
Photo Reference	IMG-2022.jpg through IMG-2024.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	1 day	\$45.00	\$135.00
Water & trash	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- SIDING

FIELD	READING
Room / Area	Exterior -- Siding
Moisture Reading	19%
Damage Type	Ceiling sag
Photo Reference	IMG-2023.jpg through IMG-2025.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & Finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- CRAWL SPACE

FIELD	READING
Room / Area	Crawl Space
Moisture Reading	26%
Damage Type	Electrical exposure risk
Photo Reference	IMG-2024.jpg through IMG-2026.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	2 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- LIVING ROOM

FIELD	READING
Room / Area	Living Room
Moisture Reading	33%
Damage Type	Water intrusion
Photo Reference	IMG-2025.jpg through IMG-2027.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	10 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	1 day	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- KITCHEN

FIELD	READING
Room / Area	Kitchen
Moisture Reading	40%
Damage Type	Drywall staining
Photo Reference	IMG-2026.jpg through IMG-2028.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- PRIMARY BEDROOM

FIELD	READING
Room / Area	Primary Bedroom
Moisture Reading	47%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2027.jpg through IMG-2029.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BEDROOM 2

FIELD	READING
Room / Area	Bedroom 2
Moisture Reading	54%
Damage Type	Flooring buckling
Photo Reference	IMG-2028.jpg through IMG-2030.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & Finish	45 sq ft	\$1.75	\$78.75