Multimodal Construction Intelligence Platform
Safety audits, crack diagnostics, cost and valuation, and weather-aware site protocols.

Safety & PPE | Crack diagnostics | Planning & valuation | Site assistant

Site safety and PPE audit

Upload a site photo

construu...worker.jpg
28.6KB



Run safety audit

75/100
Safety score

1
Workers detected

Needs Improvement
Overall status

PPE checklist

Helmet	High-vis vest	Steel-toe boots	Safety harness
Present	Present	Missing	Missing

Identified hazards

Low **Lower body and feet not visible in the frame, making steel-toe boots unverified.**

Remedy: Ensure full-body visibility during safety audits to verify footwear compliance with OSHA 1926.96 / IS 15298.

Medium **Working at height / roof proximity hazard not fully assessed due to cropped framing, though harness cannot be seen.**

Remedy: If working at heights above 6 feet (OSHA) / 2 meters (IS 3764), mandate a full-body safety harness tied off to an approved anchor point.

One worker is detected wearing a hard hat, high-visibility vest, work gloves, and safety glasses. Steel-toe boots and a safety harness are not visible in the current cropped frame and are marked as false. Overall compliance needs improvement pending verification of footwear and fall protection if at height.

Download JSON report