
Multimodal Construction Intelligence Platform
Safety audits, crack diagnostics, cost and valuation, and weather-aware site protocols.

Safety & PPE | Crack diagnostics | Planning & valuation | Site assistant

Crack diagnostics and structural integrity

Upload a concrete or wall surface photo

concret...rack 2.jpg
34.9KB



Diagnose defect

Structural Shear
Defect type

2.5 mm
Estimated width

85/100
Severity score

Urgency: Immediate - restrict access

Probable root causes

Recommended repairs

- Differential foundation settlement
- Excessive structural shear stresses exceeding concrete tensile strength
- Inadequate reinforcement detailing or overloading per IS 456

- Conduct thorough structural load assessment and non-destructive testing
- Install crack monitors to track active movement
- Perform structural retrofitting, epoxy pressure injection, or underpinning per IS 13935 guidelines

Severe wide cracking network indicating significant structural movement and potential shear failure. Immediate safety assessment and restricted access are required.

AI screening only. Structural decisions need inspection by a licensed engineer.

Download JSON report