MOLD BUSTERS®
DECONTAMINATION EXPERTS | EST. 2005



PROJECT CLEARANCE REPORT

Report Prepared for: [client name removed]

Address of the Inspected Property: **2575 Rue de la Canardière, Laval, QC**

Inspected by:



Joshua Lebrun, CMI
Indoor Environmental Inspector

Date: September 16, 2026

Created by:



Goran Petkoski
Administrative Client Support

Date: September 17, 2026

Reviewed by



Stefan Ivkovic
Administrative Client Support

Date: September 17, 2026

www.bustmold.com

TABLE OF CONTENTS

01

COMPANY PROFILE

02

EQUIPMENT

03

VISUAL & DIAGNOSTIC RESULTS

04

PHOTOGRAPHIC EVIDENCE

05

CONCLUSION AND RECOMMENDATION

⚠ Disclaimer

The results and interpretation of our inspection and sampling procedures are based on conditions present at the time of the assessment. All efforts were made to ensure accuracy in the collection, and observation of relevant data within the inspected area(s). Unless otherwise stated, the assessment is non-invasive in nature, and inaccessible areas (i.e., behind wall cavities, under sub-floor materials, etc.) may contain concerns not presented in this report due to the restrictions and limitations of the assessment provided. The information and recommendations presented in this report are based on data available at the time of the inspection. Any recommendations made in this report are made, in good conscience and in accordance with the following guidelines:

- Residential Mold Removal Guidelines, 1st Edition, Mold Busters, 2019;
- S520 Standard and Reference Guide for Professional Mold Remediation, IICRC, 2015;
- Mould Guidelines for the Canadian Construction Industry, Canadian Construction Association, 2004;
- ANSI/ASHRAE 62.2-2010, Ventilation for Acceptable Indoor Air Quality in Low-Rise Residential Buildings, American Society of Heating, Refrigeration, and Air-Conditioning Engineers, 2010

Health Canada considers indoor mould growth to be a significant health hazard. The level of concern depends on the extent of mould, how long it has been present and the sensitivity and overall health of the residents. Some people are more susceptible than others. Health Canada recommends controlling dampness indoors and cleaning up any mould regardless of the type of mould present.

01

COMPANY PROFILE

Mold Busters: Decontamination Experts

Mold Busters is a Canadian-owned and operated mold inspection, testing, and removal company that has been established since 2005.

Based in Ottawa, Mold Busters have been servicing residential, commercial, and government clients, promptly dealing with their indoor environmental concerns with professionalism and precision. Their dedication to providing excellent service to their customers have allowed them to grow, opening locations across Ontario, Quebec and the Asia-Pacific.

MOLD BUSTERS SPECIALIZES IN THE FOLLOWING SERVICES:

- Visual & diagnostic mold assessments
- Mold testing
- Comprehensive reports

- Mold removal
- Remediation
- Disinfection

- Non-viable, and viable air quality testing

- Odor removal

- Asbestos testing

- Ventilation
- Duct cleaning
- Air exchanger installation

- Thermal imaging inspections

Mold Busters does not sub-contract any inspection or remediation work, unless otherwise stated. All Mold Busters inspectors are trained through the National Association of Mold Professionals, InterNACHI, IAQA, or the IICRC.

Please visit our website for more information: www.bustmold.com

02

EQUIPMENT

Mold Busters utilizes a variety of diagnostic and sampling equipment during the assessment. The type of equipment used for each assessment is determined by the technician conducting the inspection. All equipment is regularly calibrated to ensure accuracy in the results. Common diagnostic equipment utilized includes:

1. Precision Hygro-Thermometer - Extech RH490

This measures relative humidity, temperature, and dew point levels. As per ASHRAE guidelines, relative humidity levels above 65% are indicative of a potential for mold propagation.

2. Pinless Moisture Meter – Extech MO257

This non-invasive moisture meter measures the moisture content of a building material. Typically, the MC (moisture content) of wood & drywall should be below 16%.

3. FLIR One Pro

This is a thermal imaging camera attachment that assists in determining heat differentials, or thermal anomalies within building materials.

4. Particle Scan Pro - IQAir

This is an airborne laser particle counter which gives an instantaneous reading of solid particulates between

0.3µm and 5.0µm with a refresh rate of 0.025CFM.

5. Instant Swab Analysis

This is an instant swab analysis utilized to confirm or deny the presence of biological contaminants, such as bacteria, fungi (mold), etc., on a discolored surface area. This is a non-speciating diagnostic swab test.

6. Buck BioAire – Bioaerosol Sampling Pump B520 used with Air-O-Cell cassettes

This is a compact 5-20 LPM controlled flow sampling pump for bioaerosol sampling, which accommodates Air- O-Cell cassettes. This is utilized for air quality testing. All sampled cassettes are sent to an independent, government accredited laboratory that specializes in microbial analysis.

All technicians are equipped with the necessary PPE (Personal Protective Equipment), lighting, and accessibility tools required to perform most indoor assessments. Additional equipment or specialized diagnostics may be utilized on requested projects, as needed. The technician reserves the right to use any or none of the equipment listed or unlisted during the assessment process.

Although there have been many changes in the world due to COVID-19, our commitment to providing safe and effective services holds strong. As such, our highly trained and experienced staff are taking additional precautions to keep you safe during in-person appointments and remediation projects. To view all our Covid-19 Safety and Prevention Measures, please visit https://www.bustmold.com/covid-19/.

03

VISUAL & DIAGNOSTIC RESULTS

We are pleased to announce the successful completion of the remediation project at 2575 Rue de la Canardière

• Upon finalization of the project, our Project Supervisor conducted a rigorous post-remediation verification process. This included a thorough visual inspection of the treated areas to ensure the effectiveness of the remediation efforts.

• A detailed visual inspection was carried out to further confirm the success of the remediation process. The inspection revealed no signs of fungal growth in any of the treated areas, further substantiating the effectiveness of our remediation efforts.

• Based on these comprehensive evaluations, the Project Supervisor has confidently declared the project complete. The treated areas have been awarded a clearance grade of 4, signifying a high standard of remediation and a successful restoration to a healthy, mold-free state.

• In addition to this, the Project Supervisor has provided recommendations to maintain the current state of the treated areas and prevent any potential resurgence of fungal growth. These guidelines are crucial in ensuring the long-term effectiveness of the remediation efforts and maintaining a healthy and safe environment.

• This certificate hereby acknowledges the successful completion of the remediation project at 2575 Rue de la Canardière. All treated areas have been thoroughly inspected and confirmed to be free of mold. We commend the efforts of all those involved in the project and express our gratitude for the opportunity to provide our services. We remain available for any further assistance or queries.

04

PHOTOGRAPHIC EVIDENCE

Photographs taken by the technician during the assessment

Location: 2575 Rue de la Canardière, Laval, QC

Date: September 16, 2026

Pre-Remediation Photos



Pre-Remediation Assessment



Pre-Remediation Assessment

Active Remediation Photos



Remediation Project




Remediation Project



Remediation Project



Remediation Project





Remediation Project




Remediation Project



Swab test #1



Swab test #2







Instant swab test revealed negative results for biological contaminant



Remediation Project



Remediation Project

Post-Remediation Photos




Post-Remediation Verification



Post-Remediation Verification




Post-Remediation Verification



Post-Remediation Verification



Post-Remediation Verification






Post-Remediation Verification



Post-Remediation Verification

05

CONCLUSIONS & RECOMMENDATIONS



Grade Level for : 2575 Rue de la Canardière

Grade 4

The conditions at the time of the post-remediation assessment revealed that optimal clearance criteria had been met, and that no additional remediation or disinfection work would be required in the treated space(s) at this time.

To maintain and/or further improve these current indoor environmental conditions, it is recommended to:

- It is recommended to regulate the levels of relative humidity to be between 30-50% year-round;

- It is recommended to ensure there is adequate ventilation at all times.



Joshua Lebrun, CMI

Indoor Environmental Inspector

06

APPENDIX - KNOWLEDGE BASE



Everything You Need to Know About Mold



The Mold Library



Residential Mold Removal Guidelines



Asbestos in Canada: A Homeowner's Handbook



The Ultimate Mold Prevention Guide



Indoor Air Quality



Mold Videos

Copyright © 2026 Bust Mold Inc. All rights reserved.