MOLD BUSTERS®
DECONTAMINATION EXPERTS | EST. 2005



VIRTUAL ASSESSMENT REPORT

Report Prepared for: [client name removed]

Address of the Inspected Property: **1922 S 6th St, Philadelphia, PA 19148, USA**

Inspected by:



Luka Markovic, MSC ME, CMI
Indoor Environmental Inspector

Date: August 31, 2026

Created by:



Stefan Ivkovic
Administrative Client Support

Date: September 1, 2026

Reviewed by



Goran Petkoski
Administrative Client Support

Date: September 1, 2026

www.bustmold.com

TABLE OF CONTENTS

01

COMPANY PROFILE

02

VISUAL RESULTS

03

PHOTOGRAPHIC EVIDENCE

04

CONCLUSION AND RECOMMENDATION

⚠ Disclaimer

The results and interpretation of our inspection and sampling procedures are based on conditions present at the time of the assessment. All efforts were made to ensure accuracy in the collection, and observation of relevant data within the inspected area(s). Unless otherwise stated, the assessment is non-invasive in nature, and inaccessible areas (i.e., behind wall cavities, under sub-floor materials, etc.) may contain concerns not presented in this report due to the restrictions and limitations of the assessment provided. The information and recommendations presented in this report are based on data available at the time of the inspection. Any recommendations made in this report are made, in good conscience and in accordance with the following guidelines:

- Residential Mold Removal Guidelines, 1st Edition, Mold Busters, 2019;
- S520 Standard and Reference Guide for Professional Mold Remediation, IICRC, 2015;
- Mould Guidelines for the Canadian Construction Industry, Canadian Construction Association, 2004;
- ANSI/ASHRAE 62.2-2010, Ventilation for Acceptable Indoor Air Quality in Low-Rise Residential Buildings, American Society of Heating, Refrigeration, and Air-Conditioning Engineers, 2010

Health Canada considers indoor mould growth to be a significant health hazard. The level of concern depends on the extent of mould, how long it has been present and the sensitivity and overall health of the residents. Some people are more susceptible than others. Health Canada recommends controlling dampness indoors and cleaning up any mould regardless of the type of mould present.

01

COMPANY PROFILE

Mold Busters: Decontamination Experts

Mold Busters is a Canadian-owned and operated mold inspection, testing, and removal company that has been established since 2005.

Based in Ottawa, Mold Busters have been servicing residential, commercial, and government clients, promptly dealing with their indoor environmental concerns with professionalism and precision. Their dedication to providing excellent service to their customers have allowed them to grow, opening locations across Ontario, Quebec and the Asia-Pacific.

MOLD BUSTERS SPECIALIZES IN THE FOLLOWING SERVICES:

- Visual & diagnostic mold assessments
- Mold testing
- Comprehensive reports

- Mold removal
- Remediation
- Disinfection

- Non-viable, and viable air quality testing

- Odor removal

- Asbestos testing

- Ventilation
- Duct cleaning
- Air exchanger installation

- Thermal imaging inspections

Mold Busters does not sub-contract any inspection or remediation work, unless otherwise stated. All Mold Busters inspectors are trained through the National Association of Mold Professionals, InterNACHI, IAQA, or the IICRC.

Please visit our website for more information: www.bustmold.com

02

VISUAL RESULTS

Objectives

Mold Busters conducted a virtual inspection at 1922 S 6th St, Philadelphia, PA 19148, USA, on August 31, 2026.

The objectives of the assessment were to:

1. Visually inspect areas of the property to identify any potential indoor environmental concerns;
2. Determine the source(s) and extent of these concerns, if present;
3. Establish an appropriate action plan and/or provide recommendations for improvement, if necessary.

Diagnostic Results

The technician made the following observations during his inspection of the property 1922 S 6th St, Philadelphia, PA 19148, USA, ON:

LOCATION:Unit

GENERAL OBSERVATIONS:

• The client reached out to Mold Busters for assistance in interpreting the results of indoor air quality and surface tests, indicating a proactive approach towards addressing potential mold issues within their property.

• Analysis of the report revealed an elevated count of Aspergillus/Penicillium group and Chaetomium, as well as the presence of Stachybotrys, commonly known as Black mold, within habitable areas. This finding is significant due to the health risks associated with these types of molds.

• A tape lift sample taken from the basement sub-floor confirmed the presence of Aspergillus and Cladosporium. These findings suggest that there may be underlying moisture issues or insufficient ventilation contributing to mold growth in this area. • The client has reported experiencing health-related issues which they suspect could be linked to the identified mold problem. This correlation between environmental factors and personal health underscores the importance of addressing any existing mold concerns promptly to ensure occupant safety and well-being.

03

PHOTOGRAPHIC EVIDENCE

Photographs taken by the technician during the assessment

Location: 1922 S 6th St, Philadelphia, PA 19148, USA

Date: August 31, 2026

04

CONCLUSIONS & RECOMMENDATIONS

The following recommendations are based on the technician's visual observations at the time of the inspection within the property at 1922 S 6th St, Philadelphia, PA 19148, USA.

• Professional mold remediation is recommended to be performed in accordance with Residential Mold Removal Guidelines. This includes the removal of any non-structural building material that is contaminated with mold, active moisture, or rot. All residual surface areas will be thoroughly disinfected using HEPA vacuums and anti-fungal treatments. This work should be performed by trained indoor environmental professionals and be verified upon completion to ensure clearance criteria have been met before any reconstruction begins.

• Consult with a medical doctor regarding health-related issues to address any potential concerns related to exposure to mold or other allergens present in the environment. • Keep humidity levels between 30-50% at all times as a preventive measure against mold growth. Maintaining this range can help inhibit the conditions conducive for mold proliferation and support overall indoor air quality.

• For topical treatment use a chemical solution of white vinegar and distilled water in a 1:1 ratio on affected surfaces where minor surface-level contamination is observed. This method can serve as an interim cleaning approach until professional services are engaged.

• Fumigate the area with food-grade Benefect decon as an additional measure for reducing microbial presence within the space, ensuring it complements other remediation efforts effectively without introducing harmful chemicals into living environments.

Please note that every individual will react differently to mold. The severity of the reaction will depend on factors such as the individual's immune system, exposure threshold, type of mold species present in the space, and duration of exposure. Health Canada considers indoor mold growth to be a "**significant health hazard**" and recommends that all mold, regardless of the species, be cleaned and that the underlying water or humidity problem be dealt with quickly to prevent potential health issues. (Source: *Addressing moisture and mold in your home; Canada.ca*)

If you have any questions regarding this report and the findings therein, please contact **Mold Busters** at 1-877-566-6653.



Luka Markovic, MSC ME, CMI

Indoor Environmental Inspector

05

APPENDIX - KNOWLEDGE BASE



Everything You Need to Know About Mold



The Mold Library



Residential Mold Removal Guidelines



Asbestos in Canada: A Homeowner's Handbook



The Ultimate Mold Prevention Guide



Indoor Air Quality



Mold Videos

Copyright © 2026 Bust Mold Inc. All rights reserved.