

Nonconformance report			NCR-No. 200351428		
Material No. VOLS:10257500	Ver AD	Material Description Fire Containment, Assy			
Program PW1900G Embraer Firewall	•	Design Organization Drawing & issue D:5379947-AA	Total quantity 1	Order No	
Coordinator Ann Charlott Linusson	Supplier code	Design Organization Part number & version D:5379947-AA	Reference No. 2023-166	•	

Decisions

Item	Serial number / batch	Item decision
1	44DAC02083	
2	44DAC02083	
4	44DAC02083	
5	44DAC02083	
6	44DAC02083	
7	44DAC02083	
8	44DAC02083	
9	44DAC02083	
10	44DAC02083	
11	44DAC02083	
12	44DAC02083	
13	44DAC02083	
14	44DAC02083	
15	44DAC02083	

Quality	GKN Design
Digitally signed by:	Digitally signed by:
Date:	Date:

GKN reserves all of its rights under the agreement and at law.

The information contained in this document is GKN Aerospace $\,$ Sweden AB $\,$

[©] Copyright GKN Aerospace Sweden AB. All rights reserved.



Nonconformance report				-	NCR-No. 200351428		
Material No. VOLS:10257500			Material Description Fire Containment, Assy	•			
Program PW1900G Embraer Firewall		Design Organization Drawing & issue D:5379947-AA		-	Total Quantity	Order No	
Coordinator Ann Charlott Linusson	1	Design Organization Part number & version D:5379947-AA			Reference No. 2023-166		

Defect Class	Pieces affected 1	Defect type Circularity (roundness)	Charact.No 03060
Requirement Locatio	n		
PAGE-03	Zone E15		

Serial numbers affected 44DAC02083.

Description of Nonconformance

Circularity 0.05 is 0.06 or 0.01 out of tolerance.

See attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.



Nonconformance report				NCR-No. 200351428		
Material No. VOLS:10257500			Material Description Fire Containment, Assy	-		
Program PW1900G Embraer Firewall		Design Organization Drawing & issue D:5379947-AA			Total Quantity 1	Order No
Coordinator Ann Charlott Linusson		Design Organization Part number & version D:5379947-AA			Reference No. 2023-166	

Defect Class	Pieces affected 1	Defect type Position	Charact.No 04118
Requirement Location			
PAGE-04	Zone K3		

Serial numbers affected

44DAC02083,

Description of Nonconformance

True Position |0.1|A|B|C| is 0.104 or 0.004 out of tolerance Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

GKN reserves all of its rights under the agreement and at law.

650 Ver 9



Nonconformance report					NCR-No. 200351428	
Material No. VOLS:10257500			Material Description Fire Containment, Assy			
Program PW1900G Embraer Firewall	0	Design Organization Drawing & issue D:5379947-AA			Total Quantity 1	Order No
Coordinator Ann Charlott Linusson	_	Design Organization Part number & version D:5379947-AA			Reference No. 2023-166	

Defect Class	Pieces affected 1	Defect type Position	Charact.No 08008
Requirement Location			
PAGE-08	Zone F3		

Serial numbers affected 44DAC02083,

Description of Nonconformance

4 pos True Position 0.25|A|B|C| is 0.587 or 0.337 out of tolerance Please see attached 44DAC02083 support packfor details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

GKN reserves all of its rights under the agreement and at law.

350 Ver 9



NCR-No. Nonconformance report 200351428 Material No. Material Description VOLS:10257500 ΑD Fire Containment, Assy Program Total Quantity Order No Design Organization Drawing & issue PW1900G Embraer Firewall D:5379947-AA Coordinator Design Organization Part number & version Reference No. Ann Charlott Linusson D:5379947-AA 2023-166

Item No. 5

Defect Class	Pieces affected 1	Defect type Profile of a surface	Charact.No 08028
Requirement Location	on		
PAGE-08	Zone G3		

Serial numbers affected 44DAC02083,

Description of Nonconformance

Surface profile up to 0.25 [0.010"] ABC is 0.28 mm (MAX -0.04 to MIN -0.14) or 0.03 out of tolerance.

Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.



Nonconformance report			NCR-No. 200351428	
Material No. VOLS:10257500	Ver AD	Material Description Fire Containment, Assy	•	
Program PW1900G Embraer Firewall		lanization Drawing & issue	Total Quantity	Order No
Coordinator Ann Charlott Linusson		anization Part number & version	Reference No 2023-166	

Defect Class	Pieces affected 1	Defect type Thickness	Charact.No 09003
Requirement Location PAGE-09	Zone B14		

Serial numbers affected 44DAC02083.

Description of Nonconformance

Thickness 1.2 +/- 0.1mm is 1.33 or 0.03 over tolerance.

Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

GKN reserves all of its rights under the agreement and at law.

650 Ver 9



Nonconformance report		NCR-No. 200351428			
Material No. VOLS:10257500			Material Description Fire Containment, Assy	•	
Program PW1900G Embraer Firewall			anization Drawing & issue	Total Quantity 1	Order No
Coordinator Ann Charlott Linusson	1	Design Organization Part number & version D:5379947-AA		Reference No 2023-166	

Defect Class	Pieces affected 1	Defect type Profile of a surface	Charact.No 10003
Requirement Location PAGE-10	Zone K11		

Serial numbers affected 44DAC02083.

Description of Nonconformance

Profile of a surface 0.36 |A|B|C| is 0.506 (Min - 0.078 to Max 0.253) or 0.146 out of tolerance

Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.



Nonconformance report		NCR-No. 200351428		
Material No. VOLS:10257500	Ver AD	Material Description Fire Containment, Assy	•	
Program PW1900G Embraer Firewall		lanization Drawing & issue	Total Quantity	Order No
Coordinator Ann Charlott Linusson	Design Organization Part number & version D:5379947-AA		Reference No 2023-166	

Defect Class	Pieces affected 1	Defect type Position	Charact.No 10033
Requirement Location PAGE-10	Zone C11		·

Serial numbers affected 44DAC02083.

Description of Nonconformance

12 pos True Position |0.25 |A|B|C| is 0.695 or 0.445 out of tolerance Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

GKN reserves all of its rights under the agreement and at law.

650 Ver 9



NCR-No. Nonconformance report 200351428 Material No. Material Description VOLS:10257500 ΑD Fire Containment, Assy Program Design Organization Drawing & issue Total Quantity Order No PW1900G Embraer Firewall D:5379947-AA Design Organization Part number & version Coordinator Reference No. Ann Charlott Linusson D:5379947-AA 2023-166

Item No. 9

Defect Class	Pieces affected 1	Defect type Profile of a surface	Charact.No 10035
Requirement Local	tion		
PAGE-10	Zone B3		

Serial numbers affected 44DAC02083,

Description of Nonconformance

8 Pos Profile of a surface |0.10|A|B|C| is

0.040 (+0.01 to -0.02) or 0.00 out of tolerance.

0.030 (+0.02 to -0.00) or 0.00 out of tolerance.

0.200 (+0.09 to -0.10) or 0.100 out of tolerance.

0.220 (+0.11 to -0.11) or 0.120 out of tolerance.

0.220 (+0.11 to -0.11) or 0.120 out of tolerance.

0.240 (+0.12 to -0.11) or 0.140 out of tolerance.

0.340 (+0.17 to -0.17) or 0.240 out of tolerance.

0.370 (+0.18 to -0.19) or 0.270 out of tolerance.

Pleasesee attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

Nonconformance report					NCR-No. 200351428	
Material No.		1	Material Description			
VOLS:10257500		AD	Fire Containment, Assy			
Program	Desi	ign Org	anization Drawing & issue		Total Quantity	Order No
PW1900G Embraer Firewall	D:5	D:5379947-AA			1	
Coordinator	Desi	Design Organization Part number & version			Reference No.	
Ann Charlott Linusson	D:5	37994	7-AA		2023-166	

Defect Class	Pieces affected 1	Defect type Position	Charact.No 10039
Requirement Location PAGE-10	Zone D12		

Serial numbers affected 44DAC02083.

Description of Nonconformance

23 Pos True Position |0.25 |A|B|C| is 0.469 or 0.219 out of tolerance Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

GKN reserves all of its rights under the agreement and at law.

650 Ver 9



NCR-No. Nonconformance report 200351428 Material No. Material Description VOLS:10257500 AD Fire Containment, Assy Program Total Quantity Order No Design Organization Drawing & issue PW1900G Embraer Firewall D:5379947-AA Coordinator Design Organization Part number & version Reference No. Ann Charlott Linusson D:5379947-AA 2023-166

Item No. 11

Defect Class	Pieces affected 1	Defect type Profile of a surface	Charact.No 10042
Requirement Location PAGE-10	Zone K11		

Serial numbers affected 44DAC02083,

Description of Nonconformance

Profile of a surface \mid 0.13 \mid A \mid is 0.197 (Max 0.098 to Min -0.098) or 0.067 out of tolerance

Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

Nonconformance report		NCR-No. 200351428	}		
Material No.		Ver	Material Description		
VOLS:10257500		AD	Fire Containment, Assy		
Program	Desi	ign Org	anization Drawing & issue	Total Quantity	Order No
PW1900G Embraer Firewall	D:5	37994	I7-AA	1	
Coordinator	Desi	ign Org	anization Part number & version	Reference No	
Ann Charlott Linusson	D·5	3700/	17-ΔΔ	2023-166	

Defect Class	Pieces affected 1	Defect type Profile of a surface	Charact.No 10052
Requirement Location	on		
PAGE-10	Zone K9		

Serial numbers affected 44DAC02083.

Description of Nonconformance

4 Pos Profile of a surface |0.10|A|B|C| is

0.560 (+0.26 to -0.28) or 0.460 out of tolerance.

0.530 (+0.26 to -0.27) or 0.430 out of tolerance.

0.130 (+0.01 to -0.06) or 0.030 out of tolerance.

0.080 (+0.00 to -0.04) or 0.000out of tolerance.

Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.



NCR-No. Nonconformance report 200351428 Material No. Material Description VOLS:10257500 AD Fire Containment, Assy Program Total Quantity Order No Design Organization Drawing & issue PW1900G Embraer Firewall D:5379947-AA Coordinator Design Organization Part number & version Reference No. Ann Charlott Linusson D:5379947-AA 2023-166

Item No. 13

Defect Class	Pieces affected 1	Defect type Profile of a surface	Charact.No 11024
Requirement Location PAGE-11 Z	Zone K9		

Serial numbers affected 44DAC02083,

Description of Nonconformance

Profile of a surface |0.50|A|B|C| is 0.647 (Max 0.126 to Min -0.323) or 0.147 out of tolerance

Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.



Nonconformance report		NCR-No. 200351428		
Material No. VOLS:10257500		Material Description Fire Containment, Assy		
Program PW1900G Embraer Firewall		anization Drawing & issue	Total Quantity 1	Order No
Coordinator Ann Charlott Linusson	Design Organization Part number & version		Reference No.	

Defect Class	Pieces affected 1	Defect type Profile of a surface	Charact.No 11025
Requirement Location PAGE-11 Z	Zone G9		

Serial numbers affected 44DAC02083.

Description of Nonconformance

Profile of a surface |0.50|A|B|C| is 0.538 (Max 0.269 to Min -0.055) or 0.038 out of tolerance

Please see attached 44DAC02083 support pack for details.

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.



Nonconformance report	-	NCR-No. 200351428				
Material No. VOLS:10257500		Material Description Fire Containment, Assy	•			
Program PW1900G Embraer Firewall		 anization Drawing & issue	-	Total Quantity	Order No	
Coordinator Ann Charlott Linusson	1	 anization Part number & version		Reference No. 2023-166		

Defect Class	Pieces affected 1	Defect type Flatness	Charact.No 00010
Requirement Location PAGE-01	Zone L15		

Serial numbers affected 44DAC02083,

Description of Nonconformance

All Tolerances apply when measured in restrained condition. With Diam B restrained within 0.05 [0.002] and surface A held to 0.05 [0.002].

Flatness Measured at 0.35mm or 0.30 out of tolerance

Please see attached 44DAC02083support pack for further details

Cause of Nonconformance

For detail Root cause Analysis please refer to 8D investigation #RCA200328488.

Corrective Action (to avoid re-occurance of this Nonconformance) Planned finish: 2022-03-11

For detail corrective action / preventative action please refer to 8D investigation #RCA200328488.

GKN reserves all of its rights under the agreement and at law.

350 Ver 9