

AutoCare Service Center

4521 Oak Valley Road, Suite 12, Austin, TX 78701 | Tel: (512) 555-0147 |
License: TX-ASC-88421

VEHICLE REPAIR INVOICE

Date: April 04, 2026

Document Reference:	INV-2026-04871
Document Type:	Invoice / Repair Bill
Claimant Name:	John M. Davis
Policy Number:	POL-2026-001

Incident Details

On **April 01, 2026**, the insured vehicle (2021 Honda Civic, VIN: 1HGBH41JXMN109186) sustained damage to the front bumper and headlight assembly following a minor parking lot collision at HEB Grocery, 1205 Barton Springs Rd, Austin TX. No injuries reported. Police report filed (APD Case #2026-PL-04521).

Itemized Repair Costs

Item	Description	Parts (\$)	Labor (\$)	Total (\$)
1	Front bumper cover — OEM Honda replacement	385.00	120.00	505.00
2	Left headlight assembly — OEM replacement	210.00	85.00	295.00
3	Bumper reinforcement bar — inspection & realignment	—	95.00	95.00
4	Paint match & blend — front bumper (3-stage)	65.00	180.00	245.00
5	Diagnostic scan — pre/post repair verification	—	60.00	60.00
			Subtotal	\$1,200.00

Payment Summary

Description	Amount
Repair Subtotal	\$1,200.00
Sales Tax (8.25%)	\$0.00 (insurance exempt)
Total Due	\$1,200.00
Insurance Claim Amount	\$1,200.00

Vehicle Information

Field	Details
Year / Make / Model	2021 Honda Civic LX

VIN	1HGBH41JXMN109186
License Plate	TX LBK-4827
Odometer (at repair)	34,218 miles
Color	Aegean Blue Metallic

Technician Certification

I certify that all repairs listed above have been completed using OEM-specification parts. The vehicle has been inspected and is safe to operate. All work is covered by our 12-month warranty.

Lead Technician: Robert M. Chen, ASE Certified Master Technician #TX-44218

Shop Manager: Maria L. Gonzalez

Date of Completion: April 04, 2026

✓ VERIFIED — AutoCare Service Center (Licensed TX Automotive Repair Facility)

AutoCare Service Center — Certified Automotive Repair since 2008. All work guaranteed 12 months / 12,000 miles.