

Thermal Inspection Date: 12 Jan 2026

Thermal Findings:

1. Elevated moisture detected in bedroom wall (High moisture zone).
2. Temperature variation near window frame indicates possible water ingress.
3. Kitchen wall shows mild heat loss but no severe moisture.
4. Living room ceiling crack area shows no thermal anomaly.
5. External wall shows cold patch consistent with water seepage.
6. No electrical overheating detected.

Thermal Conclusion:

- Moisture intrusion confirmed in bedroom wall.
- Possible external water penetration source.