

Automotive QA Intelligence Monthly Report

Reporting Period: June 2026

Generated at: 2026-06-09 12:30:24

Executive Summary

During the period of June 2026, a total of **5383** failure claims were logged in the system. The breakdown of models, outbreaks by country, and critical trouble codes indicates the current quality distribution across manufacturing bases.

Quality Distribution metrics

Outbreaks by Country	Claims by Model Code
INDIA: 4652 claims BRUNEI: 191 claims TUNISIA: 101 claims SAUDI ARABIA: 71 claims UNITED ARAB EMIRATES: 70 claims URUGUAY: 40 claims COSTA RICA: 36 claims R.OF PHILIPPINES: 34 claims LEBANON: 22 claims STATE OF KUWAIT: 20 claims BAHRAIN: 15 claims ITALY: 14 claims GUATEMALA: 14 claims NIGERIA: 13 claims LIBYA: 12 claims	YFG5117D: 102 claims YSD74C4E: 96 claims YHB12D2C: 96 claims YHB23D7C: 93 claims YTB23C2V: 92 claims YTB22C2W: 92 claims YRCC6C2F: 91 claims YSDA6C2F: 89 claims YTAA1C7P: 88 claims YWD21BCJ: 87 claims YTB42C2V: 87 claims YTA26C4S: 87 claims YTB21C4W: 86 claims YSD64C2E: 86 claims YCAQAC2B: 86 claims

Top Failure Trouble Codes (DTC)

Trouble Code	Claims Count
P0420	4
P0172	4
B1600	4
U0100	3
P0500	2

Sample Quality Cases & Technical Summaries

FTIR No: FTIR/2024/9243 | Dealer: Suzuki Workshop Mumbai | Quality rating: Poor

Subject: Vehicle issue observed

Summary: Issue reported was 'Vehicle issue observed', related to causal component. Checked results found 'Unable to reproduce', and technician action was 'Customer informed'.

FTIR No: FTIR/2024/1218 | Dealer: True Value Bangalore | Quality rating: Good

Subject: AC not cooling adequately, DTC P0300 cabin temperature 8 degrees above setpoint, summer conditions city driving, compressor clutch abnormality

Summary: Issue reported was 'AC not cooling adequately, DTC P0300 cabin temperature 8 degrees above setpoint, summer conditions city driving, compressor clutch abnormality', related to causal part sensor oxygen. Checked results found 'Rattle noise reproduced during road test at 35-45kmph on uneven surface', and technician action was 'Replaced AC compressor (Part No: 95200M77KA0)'.

FTIR No: FTIR/2024/5225 | Dealer: Nexa Chennai | Quality rating: Needs Rework

Subject: Engine problem

Summary: Issue reported was 'Engine problem', related to causal part engine part. Checked results found 'Checked and found OK', and technician action was 'Repaired'.

FTIR No: FTIR/2024/1203 | Dealer: Maruti Arena Delhi | Quality rating: Good

Subject: Rust/corrosion observed on rear bumper edge, customer complaint about paint peeling at 15000km, visual defect, body panel issue

Summary: Issue reported was 'Rust/corrosion observed on rear bumper edge, customer complaint about paint peeling at 15000km, visual defect, body panel issue', related to causal part solenoid valve. Checked results found 'Paint thickness measured: defect area 68 microns, adjacent area 105 microns — below standard', and technician action was 'Replaced AC compressor (Part No: 95200M77KA0)'.

FTIR No: FTIR/2024/9246 | Dealer: Suzuki Workshop Mumbai | Quality rating: Poor

Subject: Customer complaint

Summary: Issue reported was 'Customer complaint', related to causal component. Checked results found 'Vehicle checked — problem exists', and technician action was 'Under investigation'.