

FIRST NOTIFICATION OF LOSS

Submitted by Sonoran Ridge Risk Advisors, LLC · Broker reference SRR/BR/2025/1147

NOTIFICATION

Reported by:	Desmond Achterberg
Reporting organisation:	Sonoran Ridge Risk Advisors, LLC
Role:	Producer
Email:	d.achterberg@sonoranridgerisk.example
Telephone:	+1 602 555 0510
Date reported:	10 July 2026

POLICY

Policy number:	
Insured name:	Meridian Grid Holdings, LLC
Insured organisation:	Meridian Grid Holdings, LLC
Policy type:	Builder's Risk / Installation
Period of cover:	Not stated on the notice

CLAIMANT

Claimant name:	Ironbark Constructors, Inc.
Claimant contact:	Hector Zaldivar-Boone, Executive Vice President
Claimant email:	h.zaldivar-boone@ironbarkconstructors.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy · Meridian Grid Holdings, LLC

THE LOSS

Date of loss: **7 July 2026**
Time of loss: **18:34 MST**
Loss location: **14900 South Cypress Landing Way, Mesa, AZ 85212**
Country: **United States**
Cause of loss: **Windstorm — haboob followed by a wet microburst**

Description of loss:

A haboob followed by a wet microburst crossed the site on the evening of 7 July. The site anemometer logged a peak gust of 78 mph at 18:47 and the nearby airport recorded 0.94 inches of rain in forty minutes. Two bays of partially braced erected steel racked out of plumb, about 4,400 sq ft of installed wall panel was torn off and 9,200 sq ft of roof membrane lifted and tore. With the envelope open above and to the west, two medium-voltage switchgear line-ups staged on their pads inside the north bay were exposed to blowing dust and then driving rain for roughly ninety minutes.

Property affected:

Two bays of erected structural steel racked out of plumb, three purlins and two bracing members bent; 4,400 sq ft of insulated metal panel; 9,200 sq ft of TPO membrane with 6,000 sq ft of seam separation; two MV switchgear line-ups; two generator enclosures; 180 ft of chilled water pipe and its rack; staged cable tray, busway and raised floor under a collapsed canopy; temporary works

Injuries: **0**
Fatalities: **0**
Business interruption: **No — delay in start-up not purchased on this programme**
Structural damage: **Yes — two bays of steel racked, shored and tagged out**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **5,900,000**
Repair estimate: **2,905,000**

ADDITIONAL

Incident reference: **IBC-WX-2026-0022**
Authorities involved: **None**
Potential litigation: **None indicated**