

E101 Alarm Troubleshooting - SHIBAURA MACHINE

Alarm Code E101: Injection Unit Pressure Fault

Causes: Blocked hydraulic filter, Servo valve malfunction.