INSTRUCTIONS

AF3060 INVERTER DRIVES

SIGNAL DISTRIBUTION ASSEMBLY (SDA)
331X333AAG01

OPERATION – TROUBLE SHOOTING – REPAIR

GEK-62509

ELEMENTARY 36C764834AA

These instructions do not purport to cover all details or variations in equipment nor to provide for every possible contingency to be met in connection with installation, operation or maintenance. Should further information be desired or should particular problems arise which are not covered sufficiently for the purchaser's purposes, the matter should be referred to the General Electric Company.

GENERAL ELECTRIC

ademark of the General Electric Co.

GENERAL ELECTRIC

36C764834AA
CONT ON SHEET SH NO.

UNLESS OTHERWISE SPECIFIED USE THE FOLLOWING:—				
APPLIED PRACTICES	SURFACES	TOLERANCES ON MACHINED DIMENSIONS FRACTIONS	DECIMALS	ANGLES
	✓	±	±	±

TITLE ELEMENTARY DIAGRAM
SIGNAL DISTRIBUTION ASM.

FIRST MADE FOR STANDARD LINE — AF3061
331X333AAG01



REVISIONS

No revisions are to be made to this drawing without the specific approval of the Development Engineering Section of the Speed Variator Department.

PRINTS TO	
5B(2)22	IT(BW)
5D(BK)	JA(CD)
5(QC)B	5L(BW)5
5QC(BK)5	5AE(BW)
5(TS)50	
5(S)	

MADE BY V. Babo JUNE 7, 1973
ISSUED Paul Nowak Aug. 14, 1973
APPROVALS

SPEED VARIATOR DIV OR DEPT
ERIE, PA. U.S.A. LOCATION

36C764834AA
CONT ON SHEET SH NO.

REV NO. 0

DRAWING NO.
CONT ON SHEET SH NO.

PROPRIETARY INFORMATION OF THE GENERAL ELECTRIC COMPANY

PF-660-F (4-72)
PRINTED IN U.S.A.