Safety

- Wear eye protection.
- Keep the guard closed.
- Never reach past the chuck.

Setup

- Level the machine.
- Check the coolant level.
- Home all axes.

Two Items

- Clean the way covers.
- Oil the lead screw.

One Item

- Check the spindle belt.

Prose One

l A lone line in the ordinary face is prose, not a list.

Prose Two

Some body text sits here to be read.

- Marker face, but not at the indent the document uses.