

LD-06


Assembly Instructions

Parts and Tools list Qty Name Lifting System | 1set 2 2 Foot 3 Bracket 2 4 1 Support Beam 1 4mm Hex Spanner M6*14 Screw 8 Rubber Cushion 8 ST3.5*19 Screw 2 ST4.8*19 Screw


ST4. 8*14 Screw

Table top

11




loosen the 8 screws of beam using 4MM hex spanner, adjust the beam to proper position to fit the desktop, and then lock the beam using 8 of M6*10 screws.



Attach legs to the beam using 8 of M6*14 screws.

4mm Hex Spanner

3 Attach feet to the legs using 8 of M6*14 screws.



Overturn frame and attach brackets to beam using 4 of M6*14 screws, and then fit the rubber cushions to the brackets and beams.

4mm Hex Spanner


Rubber Cushion 8PCS

M6*14 screw 8PCS

Link the frame with the Table top, using 8PCS self-tapping screws ST4.8*19.

Link the control box with Table top, using 2PCS ST4.8*14 self-tapping screws.

Link the handset with table top, using 2PCS ST3.5*19 self tapping screws.



6 Connect the control box to the handset and to the motor.