





Common definitions:

 P_a = true ambient pressure,

 P_T = true total pressure,

 P_s = instrument-corrected static press.

 P_P = instrument-corrected pitot press.

