

Transfer Junction: $H(j\omega) = \frac{V_{out}}{V_{in}}$

Phasor Multiplication: $F \cdot g = A_1 \angle \theta_1 \cdot A_2 \angle \theta_2 \longrightarrow A_1 \cdot A_2 \angle (\theta_1 + \theta_2)$

Phasor Division: $F \div g = A_1 \angle \theta_1 \div A_2 \angle \theta_2 \longrightarrow \frac{A_1}{A_2} \angle (\theta_1 - \theta_2)$