

CNC Lathe Troubleshooting Manual. Section 1: Spindle Overheat. If the spindle temperature exceeds 80C