

Maintenance Log: MLOG-001

Machine: Motor M101

Date: 2026-06-15

Engineer: Suresh Babu

Issue: Misalignment

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 2 hours

Remarks: Resolved. References SOP-005 and Machine Manual.