

Maintenance Log: MLOG-004

Machine: Motor M101

Date: 2026-06-02

Engineer: Priya Nair

Issue: Pump vibration

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 8 hours

Remarks: Resolved. References SOP-005 and Machine Manual.