

Maintenance Log: MLOG-005

Machine: Boiler B201

Date: 2026-06-02

Engineer: Karthik Raj

Issue: Boiler pressure increase

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 3 hours

Remarks: Resolved. References SOP-005 and Machine Manual.