

Maintenance Log: MLOG-020

Machine: Compressor CP01

Date: 2026-06-22

Engineer: Ravi Kumar

Issue: Motor overheating

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 5 hours

Remarks: Resolved. References SOP-005 and Machine Manual.