

Engineer Note: EN-018

Machine: Motor M101

Engineer: Suresh Babu

Observation: Recurring issues detected during peak load hours.

Practical Experience: In dealing with Conveyor jam, I found that adjusting the feed rate resolves the symptom.

Recommendation: Update the SOP to reflect modified feed rates.

Validated Solution: Yes, tested over 3 shifts.

Confidence: High