Inspection report - FS-DEMO-0001. Generated 10/13/2026, 3:36:44 PM. Final review completed 10/13/2026, 3:36:45 PM by Inspector.

Inspection overview

Claim / inspection reference: FS-DEMO-0001
Property: 100 Sample Street, Testville, ST, 00000
Insured / contact: Alex Example (fictional)
Property type: Single-family dwelling, 1 story, built 2004
Roof covering (as recorded): Laminated composition shingles, one layer (as observed)
Reported loss type(s): Hail, Wind, Water
Reported date of loss: 2026-09-21
Inspection date: 2026-10-02
Inspector: Not recorded
Workflow status: In progress

Areas inspected

Main dwelling: Front elevation, Right elevation, Rear elevation, Left elevation, Roof, Front slope, Rear slope, Kitchen, Living room
Detached garage: no areas recorded
Photographs recorded: 10. Observations recorded: 15.

Reported statements

- Main dwelling > Roof: Insured reported hearing hail for about 10 minutes on the evening of the reported loss date. - reported by Insured (fictional)
- Main dwelling > Kitchen (Level 1): Insured reported a brown stain appearing on the kitchen ceiling two days after the storm. - reported by Insured (fictional) (Damage observed)

Observations by area

Main dwelling > Front elevation
- Front elevation siding and windows: no visible dents, cracks or tears. (Component: Siding; No damage observed; Photo 1)
  Photo 1 filed under this area.

Main dwelling > Right elevation
- Window screen on right elevation: no tears observed. (Component: Window screen; No damage observed)
- Window screen on right elevation has a small tear near the lower corner. (Component: Window screen; Damage observed; Photo 5)
  Photo 5 filed under this area.

Main dwelling > Rear elevation
- Rear gutter has multiple dents along the front face. (Component: Gutter; Damage observed; Photo 4)
  Photos 3, 4 filed under this area.

Main dwelling > Left elevation
- Left elevation siding: no visible damage. (Component: Siding; No damage observed; Photo 2)
  Photo 2 filed under this area.

Main dwelling > Roof
- Roof covering is laminated composition shingle, one layer, granule loss visible at several locations. (Component: Roof covering; Damage observed; Photo 6; Measurements: Roof plane Front slope: 900 sq ft [measured]; Roof plane Rear slope: 900 sq ft [measured])
  Photo 6 filed under this area.

Main dwelling > Front slope
- Front slope test square: 9 circular marks with granule displacement caused by hail. (Component: Roof covering; Damage observed; Photos 7, 8; Measurements: Roof plane Front slope: 900 sq ft [measured])
  Photos 7, 8 filed under this area.

Main dwelling > Rear slope
- Rear slope: no marks found in test area. (Component: Roof covering; No damage observed; Measurements: Roof plane Rear slope: 900 sq ft [measured])

Main dwelling > Kitchen (Level 1)
- Kitchen ceiling has a brown ring-shaped stain approximately 3 ft by 2 ft near the exterior wall. (Component: Ceiling drywall; Damage observed; Photo 9; Measurements: Room Kitchen: floor 168 sq ft, walls 382 sq ft [measured])
  Photo 9 filed under this area.

Main dwelling > Living room (Level 1)
- Living room ceiling: no staining observed at the time of inspection. (Component: Ceiling; No damage observed)

Damage documentation table

Location	Component	Observed condition	Dimensions	Photos	Notes
Main dwelling > Kitchen (Level 1)	-	Insured reported a brown stain appearing on the kitchen ceiling two days after the storm.	Not recorded	None linked	Reported statement (Insured (fictional))
Main dwelling > Rear elevation	Gutter	Rear gutter has multiple dents along the front face.	Not recorded	Photo 4	Direct observation
Main dwelling > Right elevation	Window screen	Window screen on right elevation has a small tear near the lower corner.	Not recorded	Photo 5	Direct observation
Main dwelling > Roof	Roof covering	Roof covering is laminated composition shingle, one layer, granule loss visible at several locations.	Roof plane Front slope: 900 sq ft [measured]; Roof plane Rear slope: 900 sq ft [measured]	Photo 6	Direct observation
Main dwelling > Front slope	Roof covering	Front slope test square: 9 circular marks with granule displacement caused by hail.	Roof plane Front slope: 900 sq ft [measured]	Photos 7, 8	Direct observation
Main dwelling > Kitchen (Level 1)	Ceiling drywall	Kitchen ceiling has a brown ring-shaped stain approximately 3 ft by 2 ft near the exterior wall.	Room Kitchen: floor 168 sq ft, walls 382 sq ft [measured]	Photo 9	Direct observation

Measurement summary

Roof: 3 of 4 plane(s) complete. Measured roof surface area: 2,010 sq ft (20.1 squares).
  Incomplete planes (not included in the total): Right hip end - missing height.
  Linear features: ridge 20 ft, hip 44 ft, eave 160 ft.
  Estimated material quantities with waste allowance (not measured values): 10% -> 2,211 sq ft; 15% -> 2,311.5 sq ft.
Kitchen (Level 1): floor/ceiling 168 sq ft, adjusted wall 382 sq ft [measured].

Living room (Level 1): floor/ceiling 270 sq ft, adjusted wall incomplete [estimated] - missing ceiling height.

Assumptions and calculations

- Main dwelling > Living room (Level 1): Living room dimensions are paced estimates; ceiling height assumed similar to kitchen but not measured.

Preliminary interpretations (require review)

- Main dwelling > Kitchen (Level 1): Kitchen ceiling stain location may correspond to the roof area above the front slope.

Unresolved questions

- Main dwelling > Kitchen (Level 1): Was the attic accessible above the kitchen? Attic not entered during this visit.

Missing information and follow-up actions

- Follow-up: Return with working moisture meter for kitchen readings (due 2026-10-09)
- Follow-up: Measure right hip end height
- Gap: Main dwelling > Front elevation: possibly missing close-up photo
- Gap: Main dwelling > Right elevation: possibly missing overview photo
- Gap: Main dwelling > Left elevation: possibly missing close-up photo
- Gap: Main dwelling > Front slope: possibly missing overview photo
- Gap: Main dwelling > Rear slope: possibly missing overview, context, close-up photos
- Gap: Main dwelling > Kitchen (Level 1): possibly missing close-up photo
- Gap: Main dwelling > Living room (Level 1): possibly missing overview, close-up photos
- Gap: 1 photo is not assigned to an inspection area
- Gap: 1 photo has no caption
- Gap: Roof plane "Right hip end" is missing: height
- Gap: Room "Living room" is missing: ceiling height
- Gap: Room "Living room" uses estimated (not field-measured) dimensions
- Gap: Checklist item needs follow-up: Record moisture readings and affected extent

Limitations

This report documents conditions observed and information recorded during the inspection. It does not determine coverage, approve or deny a claim, set a settlement amount, or prescribe repairs. Photographs document conditions at the time they were taken and do not by themselves establish cause, coverage, or repair necessity. Reported statements are recorded as told and have not been independently verified unless noted. Preliminary interpretations are the inspector's working assessments and require review before any decision is made.

Documentation consistency issues at time of generation

Type	Issue
contradiction	Contradiction at Main dwelling > Right elevation (Window screen): recorded both as "damage observed" and "no damage observed". Review and correct one of the entries.
warning	Possible unsupported conclusion: the direct observation "Front slope test square: 9 circular marks with granule disp..." includes cause language. Consider recording the cause as a preliminary interpretation.
warning	Preliminary interpretation "Kitchen ceiling stain location may correspond to the roof a..." has no linked photographs or measurements supporting it.

Photographs




Photo 1 - Main dwelling > Front elevation
Front elevation overview with address marker

Overview - Elevation - 10/2/2026, 2:05:00 PM




Photo 2 - Main dwelling > Left elevation
Left elevation overview

Overview - Elevation - 10/2/2026, 2:06:30 PM




Photo 3 - Main dwelling > Rear elevation
Rear elevation overview

Overview - Elevation - 10/2/2026, 2:08:00 PM




Photo 4 - Main dwelling > Rear elevation
Rear gutter - dents along front face

Close-up - Gutter - 10/2/2026, 2:09:30 PM




Photo 5 - Main dwelling > Right elevation
Right elevation window screen

Close-up - Window / screen - 10/2/2026, 2:11:00 PM




Photo 6 - Main dwelling > Roof
Roof overview from front

Overview - Roof covering - 10/2/2026, 2:12:30 PM




Photo 7 - Main dwelling > Front slope
Front slope test square (10 ft × 10 ft) marked in chalk

Context - Roof covering - 10/2/2026, 2:14:00 PM




Photo 8 - Main dwelling > Front slope
Front slope - circular mark on shingle, chalk circled

Close-up - Roof covering - 10/2/2026, 2:15:30 PM




Photo 9 - Main dwelling > Kitchen (Level 1)
Kitchen overview

Overview - Room - 10/2/2026, 2:17:00 PM




Photo 10 - Unassigned
(no caption)

Other - 10/2/2026, 2:18:30 PM