


2 Dimensions, designation







 $m'=\min \max$ wrenching height. For this zone at least e shall be maintained.

					v				
Thread size d		M 5	M 6	M 8	M 10	M 12	(M 14)	M 16	M 20
		=	5 	M8×1	M 10 × 1,25	M 12 X 1,5	(M 14×1,5)	M 16 × 1,5	M 20 X 1,
		=	New Control	1/2000	(M 10 × 1)	(M 10×1,25)	¥=1	-	<u></u>
		0,8	1	1,25	1,5	1,75	2	2	2,5
C	min.	1	1,1	1,2	1,5	1,8	2,1	2,4	3
$d_{\mathbf{a}}$	min.	5	6	8	10	12	14	16	20
	max.	5,75	6,75	8,75	10,8	13	15,1	17,3	21,6
$d_{\mathbf{c}}$	max.	11,8	14,2	17,9	21,8	26	29,9	34,5	42,8
$d_{\mathbf{w}}$	min.	9,8	12,2	15,8	19,6	23,8	27,6	31,9	39,9
e	min.	8,79	11,05	14,38	16,64	20,03	23,36	26,75	32,95
h	max.	6,2	7,3	9,4	11,4	13,8	15,9	18,3	22,4
m	min.	4,7	5,7	7,6	9,6	11,6	13,3	15,3	18,9
m'	min.	2,2	3,1	4,5	5,5	6,7	7,8	9	11,1
Nominal dimension	=max.	8	10*	13	15	18	21	24	30
9	min.	7,78	9,78	12,73	14,73	17,73	20,67	123,67	29,16
r 2)	max.	0,3	0,36	0,48	0,6	0,72	0,88	0,96	1,2

The sizes in brackets should be avoided, if possible.

¹⁾ P = pitch of coarse thread as specified in DIN 13 Part 12.

²⁾ Radius r shall apply both for the edges of adjoining flats and for the transition between hexagon corners and flange.