


DATA OUTPUT AND SOFTWARE











MEASUREMENT DATA MANAGEMENT AND ANALYSIS SOFTWARE CODE 7317



Make inspection plan

■ Define the dimensions, tolerances, control range and other parameters of workpieces



Data acquisition










4	Back Add Recon	f +N Report View Report Pr	int Data Analysis								OBy Quarter ○By Year 2022-07-01 ~ 23:59:59 😩	Refresh	Data ; Cursor
Seq	Data Hember Code	Data Member Name	Measuring Tool	. 1	2	3	4	5		Ø16			
				2022-06-08 10:58:07	2022-06-08 10:58:07	2022-06-08 10:58:08	2022-06-08 11:03:40	2022-05-08 11:10:40	202.	- 016 -			
1	DC04070001	Check type		First inspection	First inspection	Process inspection	Process inspection	Process inspection	Process in	La Pari			
2	DC04070002	Serial number		20220608001	20220608001	20220608001	20220608002	20220608002	2022		+		
3	DC04070003	Furnace No.		F00120	F00120	F00120	F00120	F00120		Niki			
	DC02070001	Flatness0.008	CHH	0.0080	0.0080	0.0080	0.0082			N N N	23		
s	DC02070002	2.39+0.01/-0.03	Vernier caliper	2.391	2.391	2.391	2.410			N N 1 N			
6	DC02070003	Verticality0.008	CHH	0.0080	0.0080	0.0080	0.0080						
7	DC02070004	2.335±0.004	Vernier caliper	2.3350	2,3350	2.3350	2.3350			1 50000	9		
	DC02070005	Outside diameter 9 = 45 ± 0.002	Hicrometer	45.0020	45.0000	45.0020	44.9977			i () () ()	Ý.		
9	DC02070006	Inner dismeter#=45±0.002	Hicrometer	45.0010	45.0010	45.0030	45.0010			1 8/771 17/1	3		
10	DC02070007	Wall thickness	700000000000000000000000000000000000000	0.0010	0.0020	0.0030	-0.0033						
		Input User		Administrator	Administrator	Administrator	Administrator	Administrator	Adm ~	-			
00	(A grant q												
	mplate Code: MTC-0-00 Related Info: INSIZE -:		e: Seeve	M.1	ten Code:	001	H. Item Non	er Drawing A					

measurement interface




SPC


■ Provide variety of quality analysis control charts



Report



Management of inspection plan





WIRELESS DATA TRANSMISSION SYSTEM

- Through wireless transmission, the measurement data can be transmitted to computers or mobile phones
- Wireless zigbee protocol, conforming to IEEE802, 2.4GHz band
 Transmission distance is 15 meter (under the condition of no obstruction and no electromagnetic interference)

transmitter receiver transmitter transmitter

Transmitter

- Connecting to digital measuring tools such as calipers, micrometers and indicators
 CR2032 battery

Code	Description	Transmitter	Connecting with measuring tool	Transmit data
7315-21	transmitter for digital calipers	transmit button signal light transmit button	signal light transmit button transmit button	 Press the transmit button on the plug of cable, can also press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once
7315-22	transmitter for large digital calipers	transmit button	signal light transmit button	 Press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once
7315-30	transmitter for digital micrometers	transmit button signal light	signal light "data" button transmit button signal light	 Press the "data" button of digital micrometer, can also press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once, at the same time, the signal light on the digital micrometer flashes once
7315-31	transmitter for digital micrometers		"data" button signal light	 Press the "data" button of digital micrometer Data is transmitted once, the signal light on the digital micrometer flashes once

Continued from previous page

Code	Description	Transmitter	Connecting with measuring tool	Transmit data	
7315-50M	transmitter for digital	transmit button	signal light "DATA" button transmit button signal light for 2108, 2138, 2139 series digital indicators	 Press the "DATA" button of digital indicator, can also press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once, at the same time, the signal light on digital indicator flashes once 	
	indicators signal light	signal light transmit button	 Press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once 		
7315-51	transmitter for digital indicators	gital	"DATA" button signal light for 2108, 2138, 2139 series digital indicators	 Press the "DATA" button of digital indicator, can also press the foot switch (code 7304-7, optional) Data is transmitted once, the signal light on digital indicator flashes once 	
			foot switch (code 7304-7, optional)		
7315-60	transmitter for high precision digital indicators	transmit button	signal light transmit button	 Press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once 	
7315-80	transmitter for digital calipers/ micrometers	signal light	"SET" button transmit button	 Press the "SET" button of the calipers/micrometers, can also press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once 	

Code	Description	Transmitter	Connecting with measuring tool	Transmit data
7315-3350	transmitter for digital micrometers	transmit button	signal light transmit button	 Press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once
7315-1150	transmitter for digital height gages	transmit button	signal light transmit button	 Press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once
7315-1151	transmitter for digital height gages	transmit button	transmit button signal light	 Press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once
7315-2771	transmitter for digital protractor	transmit button signal light	signal light transmit button	 Press the transmit button of the transmitter Data is transmitted once, the signal light of the transmitter flashes once
7315-8301	transmitter for electronic balances	transmit button	signal light transmit button "" button back	■ Press the "心" transmit button of the electronic balances, can also press the transmit button of the transmitter ■ Data is transmitted once, the signal light of the transmitter flashes once

Receiver (keyboard signal)

- For computers and mobile phones
 Recognized as HID keyboard device, the transmitted data is recognized by computers or mobile phones as keyboard input data and press enter, such as 12.34 ∠.

 No need to install drivers and softwares

 ■ Data can be transmitted to excel, word, txt etc.

 ■ For any softwares which can receive keyboard signal

Code	Product	Description	Remark
7315-3	USB port	single channel receiver	connected with 1 transmitter only



Code	Product	Description	Remark
7315-6	USB port—		
7315-7	type-C port	multichannel	connected with 6 transmitters, each channel
7315-8	micro USB port	receiver	has status indicator
7315-9	lightning port		

Receiver (text format, virtual com port)

- For computers with windows system
- Text format virtual com port, converted to keyboard format with supplied software
- Supplied with Excel directional input software
- Measurement data can be transmitted to excel, word, txt etc. and any software which receives keyboard signal

Code	Product	Description	Remark
7315-2	USB port antenna	multichannel receiver	connected with maximum 16 transmitters, each of them has unique identification code

Excel directional input software

- Supplied with 7315-2 receiver
- The measurement data of multiple measuring tools can be transmitted to the designated area of excel, which facilitates data management and improves efficiency

Excel directional input software (included in **7315-2**), application example 1

Set the display area of caliper at B4-B9, the readings of caliper are displayed at B4, B5...B9 Set the display area of micrometer at C4-C9, the readings of micrometer are displayed at C4, C5... C9. Set the display area of height gage at D4-D9, the readings of height gage are displayed at D4, D5... D9. Project Length Width Height Dimension and Tolerance 50±0.05 24±0.01 10+0.05/-0.06 Measuring tool Caliper Micrometer Height gage 50.02 24.004 9.98 2 50.01 24.010 10.01 3 49.99 23.990 10.02 50.00 23,996 9.99 4 50.04 24.000 10.01 6 the next data display serial of area is indicated in green workpieces

Excel directional input software (included in **7315-2**), application example 2

Set the display area of micrometer at B4-C9, data input is from the left to the right,

the readings of micrometer are displayed at B4, C4, B5, C5... B9, C9.

Set the display area of caliper at D4-D9,

the readings of caliper are displayed at D4, D5... D9.


Set the display area of depth gage at E4-E9, the readings of depth gage are displayed at E4, E5... E9. Project External diameter1 External diameter2 Depth Length Dimension and Tolerance Ф23+0.01/-0.02 Ф21+0.01/-0.02 50±0.04 28±0.05 Depth gage Measuring tool Micrometer Micrometer Caliper 23.010 21.008 2 23.010 21.000 49.98 .98 3 22.999 21.000 4 23.007 20.998 5 23,000 20.985 28.01 50.01 6 23.008

serial of the next data display workpieces area is indicated in green




DATA OUTPUT CABLES (TEXT FORMAT, VIRTUAL COM PORT)

1) Data output cables with transmit box







Single transmit (can be switched to continuous transmit

single transi	nit (can be switci	ned to continuous				
Code	Description	Plug to measuring tool	Plug to computer	Connecting with measuring tool	Transmit data	
7305-21 7305-R21	cable for - digital calipers (length 3m)			transmit button	 Press the transmit button on the plug of cable, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once 	
7305-22	-22 cable for large digital calipers		■ Press the transmit button of the transmit box, or press the foot switch			
7305-R22	(length 2.5m)				Data is transmitted once, the signal light of the transmit box flashes once	
7305-30	cable for digital	cable for digital micrometers (length 2.5m)		signal light	Press the "data" button of digital micrometer, can also press the transmit button of the transmit box, or press the foot switch	
7305-R30				"data" button	Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on the digital micrometer flashes once	
7305-31	cable for digital	cable for digital	î î		"data" button signal light	Press the "data" button of digital micrometer, can also press the transmit button of the transmit box, or press the foot switch
7305-R31	(length 2.5m)			back	Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on the digital micrometer flashes once	

Continued from previous page

Code	Description	Plug to measuring tool	Plug to computer	Connecting with measuring tool	Transmit data
7305-50M	cable for				 Press the transmit button of the transmit box, or press the foot switch
7305-R50M	digital gages (length 2.5m)				 Data is transmitted once, the signal light of the transmit box flashes once
7305-1150	cable for digital height gages				 Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once
7305-R1150	(length 2.5m)				



7305-40M

Continuous transmit (can be switched to single transmit)


Code	Description	Plug to measuring tool	Plug to computer	Connecting with measuring tool	Transmit data
7305-40M	cable for digital indicators (length 2.5m)			for 2108, 2138, 2139 series digital indicators	Continuous transmit is controlled in software Single transmit: Press the "DATA" button of digital indicator, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on digital indicator flashes once Note: long press transmit button to zero the digital indicators; software of data transmit is included
				for other digital indicators	Continuous transmit is controlled in software Single transmit: Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once Note: long press transmit button to zero the digital indicators; software of data transmit is included



Code	Description	Plug to measuring tool	Plug to computer	Connecting with measuring tool	Transmit data
7305-R40M	cable for digital indicators (length 2.5m)			for 2108, 2138, 2139 series digital indicators	Continuous transmit is controlled in software Single transmit: Press the "DATA" button of digital indicator, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on digital indicator flashes once Note: long press transmit button to zero the digital indicators; software of data transmit is included
	(iongui 2.om)			for other digital indicators	Continuous transmit is controlled in software Single transmit: Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once Note: long press transmit button to zero the digital indicators; software of data transmit is included

Software (included in 7305-40M and 7305-R40M)

- Real-time display
- Tolerance setting, automatic judgment, out-of-tolerance alarm
- Real time statistics: max, min, average, Go/No-Go number
- Can save results as Excel



communication protocol

- Baud: 9600bps Data bit: 8 Stop bit 1 Check bit: None No flow control
- Data output format



Data format example Display Output
1.234 → +0001.234 ∠
-1.234 → -0001.234 ∠

■ Data output format with ID number

 D1
 D2
 D3
 D4
 D5
 D6
 D7
 D8
 D9
 D10
 D11
 D12
 D13
 D14
 D15
 D16
 D17
 D18
 D19
 D20
 D21
 Blank +or- Data section (floating point) CR ID number

Data format example Display Output
1.234 → 4109210605 +0001.234 ✓
-1.234 → 4109210605 -0001.234 ✓

- The data transmission mode can be switched: single or continuous;
 - The data output format can be switched: with ID number or without ID number; Data of digital indicators can be transmitted

by instruction:

The digital indicators can be zeroed by instruction

■ Pin definition of RS232 plug:



54321 9876

Pin No.	Symbol	Description
2	TXD	Data OUT
3	RXD	Data IN
4	VDD	+5V Power
5	GND	Ground

2) Data output cables without transmit box



application



Single transmit

Code	Description	Plug to measuring tool	Plug to computer	Connecting with measuring tool	Transmit data
7305-G60	cable for high precision digital indicators (length 3m)			"DATA" HINSUZA BUTTON TO THE PARTY OF THE PA	■ Press the "DATA" button of high precision digital indicator
7305-G3350	cable for digital micrometers (length 3m)	-111		"DATA" button	■ Press the "DATA" button of digital micrometer

communication protocol

- Baud: 9600bps Data bit: 8 Stop bit 1 Check bit: None No flow control
- Data output format D1 D2 D3 D4 D5 D6 D7 D8 D9 D10 +or- Data section (floating point) CR


Data format example Display Output 1.234 -+ +0001.234 ---1.234 -- -0001.234 /- ■ Data of high precision digital indicators can be transmitted by instruction: The high precision digital indicators can be zeroed by instruction



DATA OUTPUT CABLES (KEYBOARD FORMAT)



7302-21



- Recognized as HID keyboard device by computer, no need to install drivers and softwares
- Data can be transmitted to Excel, Word, txt and other files (press transmit button, which is recognized by the computer as keyboard input data and press enter, such as 12.34∠)
- For any softwares which can receive keyboard signal
- Optional accessory: foot switch (code: 7304-2), hub (code: 7324-HUB4, 7324-HUB7), extension cables (code: 7325-ADD5, 7325-ADD10)

Code	Description	Plug	Connecting with measuring tool	Transmit data
7302-21	cable for digital calipers (length 3m)		transmit button	 Press the transmit button on the plug of cable, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once
7302-22	cable for large digital calipers (length 2.5m)	111		 Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once
7302-30	cable for digital micrometers (length 2.5m)	•≠#3	signal light "data" button	 Press the "data" button of digital micrometer, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on the digital micrometer flashes once
7302-31	cable for digital micrometers (length 2.5m)		signal light "data" button	 Press the "data" button of digital micrometer, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on the digital micrometer flashes once

Continued from the previous page

Code	Description	Plug	Connecting with measuring tool	Transmit data
7302-50M	cable for digital gages (length 2.5m)	-111		 Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once
7302-40M	7302-40M cable for digital indicators (length 2.5m)		for 2108, 2138, 2139 series digital indicators	 Press the "DATA" button of digital indicator, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on digital indicator flashes once Note: long press transmit button to zero the digital indicators
		V	for other digital indicators	 Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once Note: long press transmit button to zero the digital indicators
7302-60	cable for high precision digital indicators (length 2.5m)	-10:	"DATA" button	■ Press the "DATA" button of high precision digital indicator, can also press the transmit button of the transmit box, or press the foot switch ■ Data is transmitted once, the signal light of the transmit box flashes once
7302-3350	cable for digital micrometers (length 2.5m)	-101	"DATA" button	 Press the "DATA" button of digital micrometer, can also press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once
7302-1151	cable for digital height gages (length 2.5m)	-111	15186	 Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once
7302-SPC7	cable for digital height gages (length 2.5m)		OVER BING	 Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once

+INSIZE-


Continued from the previous page

Code	Description	Plug	Connecting with measuring tool	Transmit data
	cable for weighing scales (length 2.5m)		back for 8301 and 8305 series electronic balances	■ Press the "心" button of electronic balances, can also press the transmit button of the transmit box, or press the foot switch ■ Data is transmitted once, the signal light of the transmit box flashes once
7302-8001		for 8001-6D, 8001-15D, 8001-30D series weighing scales and 8501 series platform scales	 Press the transmit button of the transmit box, or press the foot switch Data is transmitted once, the signal light of the transmit box flashes once 	
7302-8304	cable for electronic balances (length 3m)		back back back	■ Press the "⇔" button of electronic balances, can also press the transmit button of the transmit box, or press the foot switch ■ Data is transmitted once, the signal light of the transmit box flashes once

DISPLAY UNIT CODE 7106-1A









MULTICHANNEL INTERFACE BOXES

REFER TO PAGE 262 FOR DETAILS



7107-1


connected with digital indicators



HUBS



application





7324-H	II ID 4
/ 3Z4-F	IUD4

7324-HUB7

Code	Description	Applicable products
7324-HUB4	4-channel hub (length 0.2m, USB computer plug)	7302 series data cables
7324-HUB7	7-channel hub (length 1m, USB computer plug)	7305 series data cables (USB plug)

■ For USB plug data cable

EXTENSION CABLES







Code	Description	Applicable products
7325-ADD5	data extension cable (length 5m, USB plug)	7302 series data cables
7325-ADD10	data extension cable (length 10m, USB plug)	7305 series data cables (USB plug)

application





7304-2

FOOT SWITCH

■ For data transmission

Code	Description	Applicable products
7304-2	data transmission foot switch with cable (length 2m)	7302 series data cables

7327-FS 7327-SW

Code	Description
7327-FS	foot switch for OK/NG input
7327-SW	hand switch for OK/NG input

- Used with **7317** software, output OK or NG

 USB plug, length 1.5m

OK/NG INPUT SWITCHES

