

TITLE: CPC Live Stream Video Config

TO:
BY:
DATE:

Issue
Recover from Spring 2025 Live Stream Problems -- suspected lightening strike

CURRENT CONDITION
RESOLVED Streaming is DOWN RESOLVED When Restored (Encoder Replaced) Audio Level is low to unusable RESOLVED Camera 1 HDMI Connection is intermittent Operating Table and Camera 1 Locations interferes with Choir

GOAL

PRIORITIZATION ANALYSIS

ROOT-CAUSE ANALYSIS

ACTIVITIES / COUNTERMEASURES	WHAT	WHO	WHEN
	1. Replaced Encoder	Jim / Kurt	
	2. Changed audio path to L & R Line into switcher	Jim C. / Kurt / Jim M. / Steve	
	3. Adjusted Sound Board Level to ~ Max	Jim C.	
	4. Adjusted Encoder Audio Level to +10	Steve	
	5. Replaced Camera 1 HDMI Cable	Mike	
	6. Address interference with choir		

RESULTS
System is usable

STANDARDIZATION
Document and Backup Device Connection and Configuration As Built -- As Installed -- As Configured