Q76.	The seven traditional, fundamental quality control tools consist of Check sheet, Pareto	
	chart, Stratification, Scatter Diagram, Histogram, and Control Chart.	What is the last
	(or 7th) one?	

a) Affinity diagramb) Cause and effect diagramc) Relation diagramd) Tree diagram