US. OSHA Table Z-1 Permissible Exposure Limits (PEL) for Air Contaminants (29 CFR 1910.1000)

Type **CUMENE (CAS 98-82-8)** PEL 245 mg/m3

50 ppm

Value

US. ACGIH Threshold Limit Values (TLV)

Value Components Type **CUMENE (CAS 98-82-8) TWA** 5 ppm

NIOSH. Immediately Dangerous to Life or Health (IDLH) Values, as amended

Value Components **Type CUMENE (CAS 98-82-8)** IDLH 0.9 % 900 ppm

US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) Components Value **Type CUMENE (CAS 98-82-8)** TWA 245 mg/m3

50 ppm

Biological limit values No biological exposure limits noted for the ingredient(s).

Exposure guidelines

Components

US - California OELs: Skin designation

CUMENE (CAS 98-82-8) Can be absorbed through the skin.

US - Minnesota Haz Subs: Skin designation applies

CUMENE (CAS 98-82-8) Skin designation applies.

US - Tennessee OELs: Skin designation

CUMENE (CAS 98-82-8) Can be absorbed through the skin.

US NIOSH Pocket Guide to Chemical Hazards: Skin designation

Can be absorbed through the skin. **CUMENE (CAS 98-82-8)**

US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000)

Can be absorbed through the skin. **CUMENE (CAS 98-82-8)**

Appropriate engineering

controls

Use adequate ventilation to control airborne concentrations below the exposure limits/guidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local exhaust ventilation, or other engineering controls to control airborne levels below the

recommended exposure limits/guidelines.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Hand protection Suitable chemical protective gloves should be worn when the potential exists for skin exposure.

The choice of an appropriate glove does not only depend on its material but also on other quality features and is different from one producer to the other. Nitrile gloves are recommended.

Other Wear appropriate chemical resistant clothing if applicable.

Respiratory protection If engineering controls do not maintain airborne concentrations to a level which is adequate to

protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection

Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

Observe any medical surveillance requirements. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants.

9. Physical and chemical properties

Appearance

Version: 01

Physical state Liquid.

VISCOUS LIQUID Form

Red Color

Characteristic. Odor

FIR No.: 196512 SDS US

Issue Date: 04-04-2024