## **US. ACGIH Threshold Limit Values**

Components	Туре	Value	Form
Magnesium oxide (CAS 1309-48-4)	TWA	10 mg/m3	Inhalable fraction.
Molybdenum disulphide (CAS 1317-33-5)	TWA	3 mg/m3	Respirable fraction.
		10 mg/m3	Inhalable fraction.
Tin sulphide (CAS 1315-01-1)	TWA	2 mg/m3	
Zinc sulphide (CAS 1345-05-7)	TWA	0.5 mg/m3	
Zirconium silicate (CAS 10101-52-7)	STEL	10 mg/m3	
	TWA	5 mg/m3	

## **US. NIOSH: Pocket Guide to Chemical Hazards**

Components	Туре	Value	Form	
Carbon (CAS 7440-44-0)	TWA	2.5 mg/m3	Respirable.	
Copper (CAS 7440-50-8)	TWA	1 mg/m3	Dust and mist.	
Graphite (CAS 7782-42-5)	TWA	2.5 mg/m3	Respirable.	
Silicon carbide (CAS 409-21-2)	TWA	5 mg/m3	Respirable.	
,		10 mg/m3	Total	
Tin sulphide (CAS 1315-01-1)	TWA	2 mg/m3		
Zinc sulphide (CAS 1345-05-7)	TWA	0.5 mg/m3		
Zirconium silicate (CAS 10101-52-7)	STEL	10 mg/m3		
· ,	TWA	5 mg/m3		

**Biological limit values** 

No biological exposure limits noted for the ingredient(s).

Appropriate engineering controls

Use explosion-proof electrical equipment if airborne dust levels are high. Provide adequate ventilation. Observe Occupational Exposure Limits and minimize the risk of inhalation of dust.

## Individual protection measures, such as personal protective equipment

Eye/face protection Wear approved safety goggles.

Skin protection

Hand protection Wear protective gloves. Wear protective gloves (i.e. latex, nitrile). Suitable gloves can be

recommended by the glove supplier.

Other Wear suitable protective clothing.

If engineering controls do not maintain airborne concentrations below recommended exposure Respiratory protection

> limits (where applicable) or to an acceptable level (in countries where exposure limits have not been established), an approved respirator must be worn. During dust-raising work: In the United States of America, if respirators are used, a program should be instituted to assure compliance with OSHA Standard 1910.134. Respirator type: Any powered, air-purifying respirator with a

high-efficiency particulate filter.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

Always observe good personal hygiene measures, such as washing after handling the material General hygiene considerations

and before eating, drinking, and/or smoking. Routinely wash work clothing and protective

equipment to remove contaminants.

## 9. Physical and chemical properties

**Appearance** 

Solid. Physical state

Solid (article). **Form** 

Color Grey. Odor None.

Odor threshold Not applicable. Not applicable. Ηq Melting point/freezing point Not available.

FER 4446/2 SDS US