Canada. Ontario OELs. (Control of Exposure to Biological or Chemical Agents)

Components	Туре	Value	Form
Aluminum oxide (CAS 1344-28-1)	TWA	1 mg/m3	Respirable fraction.
Barium sulphate (CAS 7727-43-7)	TWA	10 mg/m3	
Cellulose (CAS 9004-34-6)	TWA	10 mg/m3	
Graphite (CAS 7782-42-5)	TWA	2 mg/m3	Respirable fraction.
Magnesium oxide (CAS 1309-48-4)	TWA	10 mg/m3	Inhalable fraction.

Canada. Quebec OELs. (Ministry of Labor - Regulation Respecting the Quality of the Work Environment)

Components	Туре	Value	Form
Aluminum oxide (CAS 1344-28-1)	TWA	10 mg/m3	Total dust.
Barium sulphate (CAS 7727-43-7)	TWA	5 mg/m3	Respirable dust.
		10 mg/m3	Total dust.
Cellulose (CAS 9004-34-6)	TWA	10 mg/m3	Total dust.
Graphite (CAS 7782-42-5)	TWA	2 mg/m3	Respirable dust.
Magnesium oxide (CAS 1309-48-4)	TWA	10 mg/m3	Fume.

Biological limit values No biological exposure limits noted for the ingredient(s).

Appropriate engineering controls

Use explosion-proof electrical equipment if airborne dust levels are high. Provide adequate ventilation. Observe Occupational Exposure Limits and minimize the risk of inhalation of dust.

Individual protection measures, such as personal protective equipment

Wear approved safety goggles. Eye/face protection

Skin protection

Hand protection Wear protective gloves (i.e. latex, nitrile). Suitable gloves can be recommended by the glove

supplier.

Other Wear suitable protective clothing.

Respiratory protection If engineering controls do not maintain airborne concentrations below recommended exposure

limits (where applicable) or to an acceptable level (in countries where exposure limits have not been established), an approved respirator must be worn. Respirator type: Any powered,

air-purifying respirator with a high-e ciency particulate Iter.

Wear appropriate thermal protective clothing, when necessary. Thermal hazards

General hygiene considerations

Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective

equipment to remove contaminants.

9. Physical and chemical properties

Solid (article). **Appearance**

Physical state Solid. **Form** Solid. Color Gray/Brown. None. Odor

Odor threshold Not applicable. Not applicable. Melting point/freezing point Not applicable. Initial boiling point and boiling Not applicable.

range Flash point

Not applicable. Not available.

Not applicable.

Upper/lower ammability or explosive limits

Flammability limit - lower Not applicable.

(%)

Evaporation rate

Flammability (solid, gas)

FA 603 SDS Canada