Components	Туре	Value	Form
		5 mg/m3	Welding fume or pyrophoric powder
		10 mg/m3	Total
CALCIUM CARBONATE (CAS 471-34-1)	TWA	5 mg/m3	Respirable.
		10 mg/m3	Total
White mineral oil (petroleum) (CAS 8042-47-5)	STEL	10 mg/m3	Mist.
	TWA	5 mg/m3	Mist.
US. OARS. Workplace Environn	nental Exposure Level (WEEL) G	Guide	
Components	Type	Value	
Butanone oxime (CAS 96-29-7)	TWA	36 mg/m3	
		10 ppm	

Biological limit values

Appropriate engineering

controls

Use adequate ventilation to control airborne concentrations below the exposure limits/guidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local

exhaust ventilation, or other engineering controls to control airborne levels below the

recommended exposure limits/guidelines.

No biological exposure limits noted for the ingredient(s).

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Hand protection

Suitable chemical protective gloves should be worn when the potential exists for skin exposure. The choice of an appropriate glove does not only depend on its material but also on other quality features and is different from one producer to the other. Use protective gloves made of: Polyvinyl chloride (PVC). Nitrile. Neoprene.

Other Wear appropriate chemical resistant clothing if applicable.

Respiratory protection

Thermal hazards

If engineering controls do not maintain airborne concentrations to a level which is adequate to protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

Observe any medical surveillance requirements. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants. Contaminated work clothing should not be allowed out of the workplace.

9. Physical and chemical properties

Appearance

Physical state Liquid.
Form Paste.
Color GRAY
Odor Mild.

Odor threshold Not available.

pH Not available.

Melting point/freezing point -67 °F (-55 °C)

Initial boiling point and boiling Not available.

range

Flash point >199.4 °F (>93.0 °C) Tag Closed Cup

Evaporation rate <1 (BuAc=1)
Flammability (solid, gas)
Not applicable.

FIR No.: 500351 SDS US

Issue Date: 08-28-2024

Version: 01