



Conditions for safe storage, including any incompatibilities:

Keep containers tightly closed, in a cool, well-ventilated place. Store

at temperature not exceeding 125°F (52°C.).

Keep containers dry.

Keep away from open flames, hot surfaces, welding operations, and

other heat sources.

Keep away from finely divided metals such as aluminum, zinc, magnesium, and alloys containing more than 2% magnesium. Can react violently if in contact with alkali metals and alkaline earth metals

such as sodium, potassium, or barium.

SECTION 8 - EXPOSURE CONTROLS/PERSONAL PROTECTION

OSHA Permissible Exposure

Limit (PEL):

Not established

American Conference of Governmental Industrial Hygienists (ACGIH) Threshold

Limit Value (TLV):

Not established

American Industrial Hygiene Association (AIHA) Workplace Environmental Exposure Level

(WEEL):

1000 ppm 8-hour TWA

Mexichem Fluor Guideline: 1000 ppm 8-hour TWA

Appropriate engineering controls: Use ventilation to maintain safe levels. Where appropriate

engineering controls are not in place or are inadequate, wear suitable

respiratory equipment.

Eye Protection: Use chemical safety goggles or safety glasses and a face shield

when there is potential for eye contact.

Skin Protection: Take all precautions to prevent skin contact. Use gloves and

protective clothing made of material that has been found by user to be impervious under conditions of use to prevent the skin from becoming frozen from contact with liquid. User should verify impermeability under normal conditions of use prior to general use. Additional protection such as an apron, arm covers, or full body suit

may be needed depending on conditions of use.

Respiratory Protection: Not normally needed if controls are adequate. If needed, use

NIOSH/MSHA approved respirator for organic vapors. For high concentrations and oxygen-deficient atmospheres, use positive

pressure air-supplied respirator.