US. ACGIH Threshold Limit Value
---------------------------------

US. ACGIH Threshold Limit Values				
Components	Туре	Value	Form	
Zirconium dioxide (CAS 1314-23-4)	STEL	10 mg/m3		
	TWA	5 mg/m3		
US. NIOSH: Pocket Guide to Cher	nical Hazards			
Components	Туре	Value	Form	
1,4-benzenedicarbonyl dichloride polymer with 1,4-benzenediamine (CAS 26125-61-1)	TWA	3 fibers/cm3	Fiber.	
		3 fibers/cm3	Fibrous dust.	
		5 mg/m3	fibers, total dust	
		5 mg/m3	Fiber, total	
Barium sulphate (CAS 7727-43-7)	TWA	5 mg/m3	Respirable.	
		10 mg/m3	Total	
Calcium dihydroxide (CAS 1305-62-0)	TWA	5 mg/m3		
Calcium silicate (CAS 1344-95-2)	TWA	5 mg/m3	Respirable.	
		10 mg/m3	Total	
Graphite (CAS 7782-42-5)	TWA	2.5 mg/m3	Respirable.	
Mica (CAS 12001-26-2)	TWA	3 mg/m3	Respirable.	
Tin Powder (CAS 7440-31-5)	TWA	2 mg/m3		
Zinc sulphide (CAS 1345-05-7)	TWA	0.5 mg/m3		
Zirconium dioxide (CAS 1314-23-4)	STEL	10 mg/m3		

**Biological limit values** 

No biological exposure limits noted for the ingredient(s).

Appropriate engineering controls

Use explosion-proof electrical equipment if airborne dust levels are high. Provide adequate ventilation. Observe Occupational Exposure Limits and minimize the risk of inhalation of dust.

5 mg/m3

## Individual protection measures, such as personal protective equipment

Eye/face protection Wear approved safety goggles.

Skin protection

**Hand protection** Wear protective gloves (i.e. latex, nitrile). Suitable gloves can be recommended by the glove

supplier.

Other Wear suitable protective clothing.

If engineering controls do not maintain airborne concentrations below recommended exposure Respiratory protection

limits (where applicable) or to an acceptable level (in countries where exposure limits have not been established), an approved respirator must be worn. During dust-raising work: In the United States of America, if respirators are used, a program should be instituted to assure compliance with OSHA 29 CFR 1910.134. Respirator type: Any powered, air-purifying respirator with a

high-efficiency particulate filter.

TWA

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

Always observe good personal hygiene measures, such as washing after handling the material General hygiene

and before eating, drinking, and/or smoking. Routinely wash work clothing and protective considerations

equipment to remove contaminants.

## 9. Physical and chemical properties

Solid (article). **Appearance** 

Physical state Solid.

**Form** Solid (Disc pad). Color Brownish grey.

Odor None.

Odor threshold Not applicable. Not applicable. рΗ

SDS US FER 9223