SAFETY DATA SHEET

Honeywell

_	_	_	_	_	_	_	_	_	_	_	_
	V A	V A	V A	7	7 A	V A	V A	7 A 1		_	_
								ч	*		n
v	v	v	v	v	v	v	v	w	u	7	u

Version 2.7 Revision Date 05/08/2019 Print Date 08/18/2022

Neoprene gloves

Polyvinyl alcohol or nitrile- butyl-rubber gloves

Avoid skin contact with leaking liquid (danger of frostbite). Skin and body protection

Wear cold insulating gloves/ face shield/ eye protection.

Respiratory protection : In case of insufficient ventilation, wear suitable respiratory

equipment.

Wear a positive-pressure supplied-air respirator.

Vapours are heavier than air and can cause suffocation by

reducing oxygen available for breathing.

For rescue and maintenance work in storage tanks use self-

contained breathing apparatus.

Handle in accordance with good industrial hygiene and safety Hygiene measures

practice.

Ensure adequate ventilation, especially in confined areas.

Avoid contact with skin, eyes and clothing.

Remove and wash contaminated clothing before re-use.

Keep working clothes separately.

Exposure Guidelin	ies				
Components	CAS-No.	Value	Control parameters	Upda te	Basis
1,1,1,2- Tetrafluoroethane	811-97-2	TWA: Time weighted average	(1,000 ppm)		Honeywell:Limit established by Honeywell International Inc.
1110	044.07.0	T14/4	1.040/0	0007	IMEEL HO OADO
1,1,1,2- Tetrafluoroethane	811-97-2	TWA: Time weighted average	4,240 mg/m3 (1,000 ppm)	2007	WEEL:US. OARS. WEELs Workplace Environmental Exposure Level Guide
		1		1	T
1,1,1,2- Tetrafluoroethane	811-97-2	TWA: Time weighted average	4,240 mg/m3 (1,000 ppm)	2007	WEEL:US. OARS. WEELs Workplace Environmental Exposure Level Guide