# **Safety Data Sheet**

Issue Date: 2015/12 Revised: 2019/8 Side: 3/6

# 7. Handling and Storing

#### 7.1 Handling

### 7.1.1 Information for safe handling:

Avoid generating dust from this product. Clean up using methods that do not generate dust such as a HEPA vacuum or wet clean up. Avoid pneumatic removal of dust. If dust is generated, use a NIOSH approved respirator.

Minimize dust generation and accumulation.

Dust removing by suitable industrial vacuum – cleaner or central exhausting.

## 7.2 Storing

Store in a dry and ventilated storeroom. Do not store together with corrosive substances.

## 8. Exposure Controls and Personal Protection

#### 8.1.1 Exposure guidelines:

#### Mica (12001-26-2)

ACGIH: 3mg/m<sup>3</sup> TWA (respirable fraction).

OSHA: 3mg/m<sup>3</sup> TWA (respirable dust, less than 1% crystalline silica)

NIOSH: 10 mg/m<sup>3</sup> TWA (total dust ); 5 mg/m<sup>3</sup> TWA (respirable dust ).

# **Graphite (7782-42-5)**

ACGIH: 2 mg/m<sup>3</sup> TWA (respirable fraction, all forms except graphite fibers)

OSHA: 2.5mg/m<sup>3</sup> TWA (respirable dust).

NIOSH: 3mg/m<sup>3</sup> TWA (respirable dust).

## **Barium sulfate (7727-43-7)**

ACGIH: 10 mg/m<sup>3</sup> TWA

OSHA: 10 mg/m<sup>3</sup> TWA (total dust); 5 mg/m<sup>3</sup> TWA (respirable fraction)

NIOSH: 10 mg/m<sup>3</sup> TWA (total dust); 5 mg/m<sup>3</sup> TWA (respirable dust)

#### Calcium hydroxide (1305-62-0)

ACGIH: 5 mg/m<sup>3</sup> TWA

OSHA: 5 mg/m<sup>3</sup> TWA (not in effect as a result of reconsideration)

NIOSH: 5 mg/m<sup>3</sup> TWA

#### Copper (7440-50-8)

ACGIH: 0.2 mg/m<sup>3</sup> TWA (fume); 1mg/m<sup>3</sup> TWA (dusts and mists, as Cu)

OSHA: 0.1mg/m<sup>3</sup> TWA (fume, dusts, mists, as Cu)

NIOSH: 1mg/m<sup>3</sup> TWA (dusts and mists); 0.1mg/m<sup>3</sup> TWA (fume)

#### 8.1.2 Exposure limits for Particulates not otherwise regulated (Nuisance dust)

OSHA

PEL: 15mg/m<sup>3</sup> total dust; 5 mg/m<sup>3</sup> respirable fraction

ACGIH:

TLV: 10mg/m<sup>3</sup> total dust; 3 mg/m<sup>3</sup> respirable fraction

#### 8.2 General Measures for Protection and Hygienic