SAFETY DATA SHEET

Honeywell

000000011078

Version 3.2 Revision Date 08/03/2018 Print Date 05/08/2019

Do not remove screw cap until immediately ready for use.

Always replace cap after use.

Advice on protection against fire and explosion

Container hazardous when empty.

Prevent the creation of flammable or explosive concentrations of vapour in air and avoid vapour concentration higher than the

occupational exposure limits.

Keep product and empty container away from heat and

sources of ignition.

Do not pressurize, cut, weld, braze, solder, drill, grind or

expose containers to heat or sources of ignition.

Take measures to prevent the build up of electrostatic charge. Electrical equipment should be protected to the appropriate

standard.

Use explosion-proof equipment. No sparking tools should be used.

No smoking.

Storage

Conditions for safe storage,

including any incompatibilities

Pressurized container: protect from sunlight and do not expose

to temperatures exceeding 50 °C. Do not pierce or burn, even after use.

Keep containers tightly closed in a dry, cool and well-ventilated

place.

Keep away from heat and sources of ignition. Storage rooms must be properly ventilated.

Ensure adequate ventilation, especially in confined areas.

Protect cylinders from physical damage. Store away from incompatible substances.

Store in original container.

SECTION 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Protective measures : Ensure that eyewash stations and safety showers are close to

the workstation location. Do not breathe vapour.

Avoid contact with skin, eyes and clothing.

Engineering measures : Use with local exhaust ventilation.

Page 6 / 17