FORM NO. : JB-DP17-13-00 FIR No. 502117

Contact product manufacturer for latest (M)SDS ISSUE DATE : 2018/1/19

REVISED DATE:

PAGE 3/6

## **6. ACCIDENTAL RELEASE MEASURES**

PERSONAL PRECAUTION : Keep personnel away except for authorized ones from spillage area by

stretching ropes. Wear proper equipment and avoid contact with skin and

inhalation.

**ENVIRONMENTAL** : Prevent spills from entering sewers, watercourses or lower area and prevent PRECAUTION

from affecting environment. Absorb or collect the spill according to the disposal

rules.

## METHODS AND MATERIALS FOR CONTAMINANT AND CLEANING UP

: Collect it using a vacuum cleaner or dust collection equipment. Absorb or collect the spill according to the disposal rules.

## 7. HANDLING AND STORAGE

HANDLING: Wear proper equipment (antidust mask, Resistant gloves(e.g. Nitrile gloves, PVC gloves) etc.)

and avoid skin contact and inhalation of dust.

• Remove dust on work clothing using dust collection equipment etc.

· Wash hands and rinse out a mouth etc. after handling.

• Use proper dust collection equipment to prevent dust from scattering.

• Pregnant women must avoid exposure.

•If feel abnormality in the body or abnormality on the body observed, make sure to get medical

advice/attention after taking the emergency measures refer to section 4.

STORAGE: • Keep containers tightly sealed and store in a dry place.

Keep away from heat, steam pipe and sunlight.

## 8. EXPOSURE CONTROL/ PERSONAL PROTECTION

**EXPOSURE CONTROL** : Use adequate general or local exhaust ventilation to keep airborne

concentrations below the permissible exposure limits. Facilities storing or

utlizing these materials should be equipped with an eyewash and a safety shower. In case if required, install detector for flammable gases, toxic gases. (There are no

material which will create flammable gases,

CONTROL : ACGIH (TWA) Ca(OH)2: 5mg/m3 Al2O3: 10 mg/m3 PARAMETERS 1)

BaSO4:5mg/m<sup>3</sup> Mica: 3mg/m3

Graphite: 2mg/m<sup>3</sup>

Note) TWA: Time-Weighted Average, R: Respirable fraction

PERSONAL PROTECTIVE EQUIPMENT : Dust mask, Resistant gloves(e.g. Nitrile gloves, PVC gloves), Safety

goggles, Protective cloth, Supplied-air respirator