US. ACGIH Threshold Limit Value			
Components	Туре	Value	Form
Aluminum oxide (CAS 1344-28-1)	TWA	1 mg/m3	Respirable fraction.
Barium sulfate (CAS 7727-43-7)	TWA	5 mg/m3	Inhalable fraction.
Calcium silicate (CAS 1344-95-2)	TWA	1 mg/m3	Inhalable fraction.
Cellulose (CAS 9004-34-6)	TWA	10 mg/m3	
Graphite (CAS 7782-42-5)	TWA	2 mg/m3	Respirable fraction.
Magnesium oxide (CAS 1309-48-4)	TWA	10 mg/m3	Inhalable fraction.
US. NIOSH: Pocket Guide to Chen	nical Hazards		
Components	Туре	Value	Form
Barium sulfate (CAS 7727-43-7)	TWA	5 mg/m3	Respirable.
		10 mg/m3	Total
Calcium silicate (CAS 1344-95-2)	TWA	5 mg/m3	Respirable.
		10 mg/m3	Total
Cellulose (CAS 9004-34-6)	TWA	5 mg/m3	Respirable.
		10 mg/m3	Total

**Biological limit values** 

No biological exposure limits noted for the ingredient(s).

Appropriate engineering controls

Use explosion-proof electrical equipment if airborne dust levels are high. Provide adequate ventilation. Observe Occupational Exposure Limits and minimize the risk of inhalation of dust.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear approved safety goggles.

Skin protection

Hand protection Wear protective gloves (i.e. latex, nitrile). Suitable gloves can be recommended by the glove

supplier.

Wear suitable protective clothing. Other

Respiratory protection If engineering controls do not maintain airborne concentrations below recommended exposure

limits (where applicable) or to an acceptable level (in countries where exposure limits have not been established), an approved respirator must be worn. During dust-raising work: In the United States of America, if respirators are used, a program should be instituted to assure compliance with OSHA Standard 1910.134. Respirator type: Any powered, air-purifying respirator with a

high-efficiency particulate filter.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

Always observe good personal hygiene measures, such as washing after handling the material General hygiene

and before eating, drinking, and/or smoking. Routinely wash work clothing and protective considerations

equipment to remove contaminants.

## 9. Physical and chemical properties

**Appearance** Solid (article).

**Physical state** Solid. Solid. **Form** Color Light gray. Odor None.

**Odor threshold** Not applicable. pН Not applicable. Melting point/freezing point Not applicable. Initial boiling point and boiling Not applicable.

range

Flash point Not applicable.

FA607, MPV 2032 SDS US